



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
052100	INSPECT A/C FREON HOURS REPORTED					MTH 06-Jan-2010 ACH 844	150		994	148.3
053490	INSPECT RVSM GMU TEST FLIGHT ICT					MTH 28-Oct-2002	O/C			
055601 LEFT	INSPECT INSPECTION WINDSHIELD APA					MTH 10-Aug-2009 HRS 1949	24 300		31-Aug-2011 2249	17 m 9 d 171.4
055601 RIGHT	INSPECT INSPECTION WINDSHIELD APA					MTH 10-Aug-2009 HRS 1949	24 300		31-Aug-2011 2249	17 m 9 d 171.4
5-12-01 <i>0512001</i>	INSPECTION DOCUMENT 1 (INTERVAL 1A) APA					MTH 06-Jan-2010 HRS 2051	300		2351	273.4
5-12-02 <i>0512002</i>	INSPECTION DOCUMENT 2 (INTERVAL 1C) APA					MTH 01-May-2009 HRS 1898	12		31-May-2010	2 m 9 d
5-12-03 <i>0512003</i>	INSPECTION DOCUMENT 3 (INTERVAL 2C) APA					MTH 02-Oct-2009 HRS 1970	24		30-Sep-2011	18 m 8 d
5-12-04	INSPECTION DOCUMENT 4 (INTERVAL 3C)					MTH 21-Oct-2002	36			
A323101 <i>0512004 : GEAR</i>	RESTORATION (HYDROSTATIC TEST) PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE EMERGENCY PNEUMATIC STORAGE BOTTLE : INSPECTION DOCUMENT 4 (INTERVAL 3C) APA			40005320-2 3577		MTH 03-Mar-2008 HRS 1635	36		31-Mar-2011	12 m 9 d
B351005 <i>0512004 : OXY</i>	RESTORATION (HYDROSTATIC TEST) OXYGEN CYLINDER OXYGEN CYLINDER(DOT3HT1850 OR DOT3FC1850 OR ANY CYLINDER MANUFACTURED UNDER DOT-E-8162-OXYGEN BOTTLE AND REGULATOR ASSEMBLY: INSPECTION DOCUMENT 4 (INTERVAL 3C) 176274-50 10070					MTH 08-Jun-2007 HRS 1375	36	1	31-May-2010	2 m 9 d
5-12-05	INSPECTION DOCUMENT 5 (INTERVAL 5C)					MTH 21-Oct-2002	60			
B262002 LEFT ENGINE <i>0512005 : L</i>	HYDROSTATIC TEST FIRE EXTINGUISHER BOTTLE : INSPECTION DOCUMENT 5 (INTERVAL 5C) 30401102-2 48850B1					MTH 08-Jun-2007 HRS 1375	60	1	31-May-2012	26 m 9 d
B262002 RIGHT ENGINE <i>0512005 : R</i>	HYDROSTATIC TEST FIRE EXTINGUISHER BOTTLE : INSPECTION DOCUMENT 5 (INTERVAL 5C) 30401102-2 48852B1					MTH 08-Jun-2007 HRS 1375	60	1	31-May-2012	26 m 9 d
B351006	RESTORATION (HYDROSTATIC TEST) OXYGEN CYLINDER OXYGEN CYLINDER (DOT3AA)-OXYGEN BOTTLE AND REGULATOR ASSEMBLY: INSPECTION DOCUMENT 5 (INTERVAL 5C) 176274-50 10070					MTH	N/R			
B351007	RESTORATION (HYDROSTATIC TEST) OXYGEN CYLINDER OXYGEN BOTTLE (PART NUMBER 4444018-50 OR ANY CYLINDER MANUFACTURED UNDER DOT-E-10945)-OXYGEN BOTTLE AND REGULATOR ASSEMBLY: INSPECTION DOCUMENT 5 (INTERVAL 5C) 176274-50 10070					MTH	N/R			
5-12-06	INSPECTION DOCUMENT 6 (INTERVAL 6C)					MTH 21-Oct-2002	72			
A262201 COCKPIT <i>0512006</i>	SPECIAL DETAILED INSPECTION PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 6 (INTERVAL 6C) APA C352TS X624295					MTH 03-Nov-2008 HRS 1760	72	10	31-Jan-2014	46 m 9 d
5-12-07	INSPECTION DOCUMENT 7 (INTERVAL 12C)					MTH 21-Oct-2002	144			
B262202 COCKPIT <i>0512007</i>	HYDROSTATIC TEST PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 7 (INTERVAL 12C) APA C352TS X624295					MTH 03-Nov-2008 HRS 1760	144	10	31-Jan-2020	118 m 9 d
5-12-08 <i>0512008</i>	INSPECTION DOCUMENT 8 (INTERVAL 1A/2C) APA					MTH 10-Aug-2009 HRS 1949	24 300		31-Aug-2011 2249	17 m 9 d 171.4
5-12-09	INSPECTION DOCUMENT 9 (INTERVAL 2A/1C)					MTH 21-Oct-2002 HRS 0	12 600			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
A243301 0512009	FUNCTIONAL CHECK BATTERY (CAPACITY CHECK) LEAD ACID BATTERY: INSPECTION DOCUMENT 9 (INTERVAL 2A/1C)	APA		RG-380E/44LA2 40288075	MTH 15-Apr-2009 HRS 1891	12 600			30-Apr-2010 2491	1 m 8 d 413.4
5-12-10 0512010	INSPECTION DOCUMENT 10 (INTERVAL 4A/3C)	APA			MTH 03-Nov-2008 HRS 1760	36 1200			30-Nov-2011 2960	20 m 8 d 882.4
5-12-11 0512011	INSPECTION DOCUMENT 11 (INTERVAL 8A/6C)	APA			MTH 03-Nov-2008 HRS 1760	36 1200			30-Nov-2011 2960	20 m 8 d 882.4
5-12-12 0512012	INSPECTION DOCUMENT 12 (14 CFR 91.207)	APA			MTH 01-May-2009 HRS 1898	12			30-Apr-2010	1 m 8 d
5-12-13	INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM)				MTH 21-Oct-2002	24				
341060 0512013 : RVSM	FUNCTIONAL CHECK RVSM SKIN WAVINESS: INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM)				MTH 18-Apr-2008 HRS 1651	24			30-Apr-2010	1 m 8 d
341066 LEFT 0512013 : L-ADC	CALIBRATION TEST AIR DATA COMPUTER FAR 91.411: INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM)			822-1109-004 1416C	MTH 18-Apr-2008 HRS 1651	24			30-Apr-2010	1 m 8 d
341068 RIGHT 0512013 : R-ADC	CALIBRATION TEST AIR DATA COMPUTER FAR 91.411: INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM)			822-1109-004 NKXJ	MTH 18-Apr-2008 HRS 1651	24			30-Apr-2010	1 m 8 d
341074 STANDBY 0512013 : STDBY	CALIBRATION TEST ALTIMETER/AIRSPEED INDICATOR FAR 91.411: INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM)			WL102AMS6 AN945	MTH 18-Apr-2008 HRS 1651	24			30-Apr-2010	1 m 8 d
B341001 LEFT 0512013 : L	FUNCTIONAL CHECK PITOT-STATIC SYSTEM: INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM)				MTH 18-Apr-2008 HRS 1651	24			30-Apr-2010	1 m 8 d
B341001 RIGHT 0512013 : R	FUNCTIONAL CHECK PITOT STATIC SYSTEM: INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM)				MTH 18-Apr-2008 HRS 1651	24			30-Apr-2010	1 m 8 d
B345401 NO. 1 0512013 : 1	CALIBRATION TEST TRANSPONDER FAR 91.413: INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM)			010-00230-21 84306526	MTH 18-Apr-2008 HRS 1651	24			30-Apr-2010	1 m 8 d
B345401 NO. 2 0512013 : 2	CALIBRATION TEST TRANSPONDER FAR 91.413: INSPECTION DOCUMENT 13 (CFR 91.411, 91.413, AND RVSM)			010-00230-21 84306521	MTH 18-Apr-2008 HRS 1651	24			30-Apr-2010	1 m 8 d
5-12-14	INSPECTION DOCUMENT 14				MTH 21-Oct-2002	A/R				
A324103 LEFT MAIN GEAR 0512014C : L	SPECIAL DETAILED INSPECTION WHEEL ASSEMBLY LANDING GEAR WHEELS (NDI): INSPECTION DOCUMENT 14			3-1601-2 0351	MTH 20-Apr-2007 HRS 1355 LDG 864	T/C				
A324103 NOSE LANDING GEAR 0512014C : NOSE	SPECIAL DETAILED INSPECTION WHEEL ASSEMBLY LANDING GEAR WHEELS (NDI): INSPECTION DOCUMENT 14			3-1418OPT-4 5553	MTH 24-Feb-2010 HRS 2059.3 LDG 1210	T/C				
A324103 RIGHT MAIN GEAR 0512014C : R	SPECIAL DETAILED INSPECTION WHEEL ASSEMBLY LANDING GEAR WHEELS (NDI): INSPECTION DOCUMENT 14			3-1601-2 0356	MTH 20-Apr-2007 HRS 1355 LDG 864	T/C				
5-12-16	INSPECTION DOCUMENT 16				MTH 21-Oct-2002	6				
B262201 COCKPIT 0512016	WEIGHT CHECK PORTABLE FIRE EXTINGUISHER : INSPECTION DOCUMENT 16	APA		C352TS X624295	MTH 01-Dec-2009 HRS 2029	6			30-Jun-2010	3 m 8 d

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
5-12-21 0512021	INSPECTION DOCUMENT 21 (INTERVAL 2A/2C)	APA			MTH HRS	03-Nov-2008 1760	24 600		30-Nov-2010 2360	8 m 8 d 282.4
5-12-22 0512022	INSPECTION DOCUMENT 22	APA			MTH ACH	03-Dec-2009 843	800		1643	797.3
5-12-23 0512023	INSPECTION DOCUMENT 23	*CF			MTH ACH	21-Oct-2002 0	1500		1500	654.3
5-12-24 0512024	INSPECTION DOCUMENT 24 (INTERVAL1A/1C)	APA			MTH HRS	01-May-2009 1898	12 300		31-May-2010 2198	2 m 9 d 120.4
5-12-MA 05120MA	INSPECTION DOCUMENT MA (CHAPTER 4)	APA			MTH HRS	10-Aug-2009 1949	300		2248	170.4
5-12-MC 05120MC	INSPECTION DOCUMENT MC (CHAPTER 4)				MTH HRS	19-Apr-2006 1180	1200		2380	302.4
5-12-MD 05120MD	INSPECTION DOCUMENT MD (CHAPTER 4)	APA			MTH HRS	18-Jul-2007 1411	1425		2836	758.4
5-12-ME 05120ME	INSPECTION DOCUMENT ME (CHAPTER 4)	*CF			MTH LDG	21-Oct-2002 0	5000		5000	3780
5-12-MF 05120MF	INSPECTION DOCUMENT MF (CHAPTER 4)	*CF			MTH HRS	21-Oct-2002 0	2550		2550	472.4
5-12-MG 05120MG	INSPECTION DOCUMENT MG (CHAPTER 4)	*CF			MTH HRS	21-Oct-2002 0	2800		2800	722.4
5-12-MH 05120MH	INSPECTION DOCUMENT MH (CHAPTER 4)	*CF			MTH HRS	21-Oct-2002 0	3100		3100	1022.4
5-12-MI 05120MI	INSPECTION DOCUMENT MI (CHAPTER 4)	*CF			MTH HRS	21-Oct-2002 0	4950		4950	2872.4
5-12-MJ 05120MJ	INSPECTION DOCUMENT MJ (CHAPTER 4)	*CF			MTH HRS	21-Oct-2002 0	5000		5000	2922.4
5-12-MK 05120MK	INSPECTION DOCUMENT MK (CHAPTER 4)	*CF			MTH HRS	21-Oct-2002 0	5050		5050	2972.4
5-12-ML 05120ML	INSPECTION DOCUMENT ML (CHAPTER 4)	*CF			MTH HRS	21-Oct-2002 0	5050		5050	2972.4
5-12-MM 05120MM	INSPECTION DOCUMENT MM (CHAPTER 4)	*CF			MTH HRS	21-Oct-2002 0	6000		6000	3922.4
051200A E1	CHECK 1 (ROUTINE INSP)	APA			MTH HRS	10-Oct-2009 1980	150		2130	52.4
051200A E2	CHECK 1 (ROUTINE INSP)	APA			MTH HRS	10-Oct-2009 1980	150		2130	52.4
051204 E1	CHECK 2 (ROUTINE INSP)	APA			MTH HRS	10-Oct-2009 1980	300		2280	202.4
051204 E2	CHECK 2 (ROUTINE INSP)	APA			MTH HRS	10-Oct-2009 1980	300		2280	202.4
051204B E1	CHECK 4 (MPI)	ICT			MTH HRS	21-Oct-2002 0	10500		3438	1360.4
051204B E2	CHECK 4 (MPI)	ICT			MTH HRS	21-Oct-2002 0	10500		3438	1360.4
051205 E1	CHECK 5 (MPI)				MTH HRS	21-Oct-2002 0	10500		5188	3110.4
051205 E2	CHECK 5 (MPI)				MTH HRS	21-Oct-2002 0	10500		5188	3110.4
051206 E1	CHECK 6 (MPI)				MTH HRS	21-Oct-2002 0	10500		6938	4860.4
051206 E2	CHECK 6 (MPI)				MTH HRS	21-Oct-2002 0	10500		6938	4860.4
051207 E1	CHECK 7 (MPI)				MTH HRS	21-Oct-2002 0	10500		8688	6610.4
051207 E2	CHECK 7 (MPI)				MTH HRS	21-Oct-2002 0	10500		8688	6610.4

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
051208 E1	CHECK 8 (MPI)				MTH HRS	21-Oct-2002 0			10438	8360.4
051208 E2	CHECK 8 (MPI)				MTH HRS	21-Oct-2002 0	10500		10438	8360.4
051217 E1	CHECK 3 (MPI)				MTH HRS	19-Jun-2008 1688	10500		12188	10110.4
051217 E2	CHECK 3 (MPI)				MTH HRS	19-Jun-2008 1688	10500		12188	10110.4
057102 E1	INSPECT ENGINE COMPRESSOR WASH APA				MTH HRS	10-Oct-2009 1980	150		2130	52.4
057102 E2	INSPECT ENGINE COMPRESSOR WASH APA				MTH HRS	10-Oct-2009 1980	150		2130	52.4
262002 LEFT ENGINE NO.1	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) GNE			13083-5 04012012	MTH HRS	09-Feb-2007 1336	72		28-Feb-2013	35 m 6 d
262002 LEFT ENGINE NO.2	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) GNE			13083-5 04012012	MTH HRS	09-Feb-2007 1336	72		28-Feb-2013	35 m 6 d
262002 RIGHT ENGINE NO.1	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) GNE			13083-5 04012012	MTH HRS	09-Feb-2007 1336	72		28-Feb-2013	35 m 6 d
262002 RIGHT ENGINE NO.2	REPLACE FIRE EXTINGUISHER CARTRIDGE (SERVICE LIFE) GNE			13083-5 04012012	MTH HRS	09-Feb-2007 1336	72		28-Feb-2013	35 m 6 d
551010 045501	INSPECT VERTICAL FIN FOR CRACKS AROUND FASTENERS,MAIN SPAR CAP AT UPPERMOST ATTACHMENT HOLE #1 *CF				MTH HRS	21-Oct-2002 0	15000	15	15000	12922.4
551020 045502	INSPECT VERTICAL FIN FOR CRACKS AROUND FASTENERS,REAR SPAR CAP AT UPPERMOST ATTACHMENT HOLE #1 *CF				MTH HRS	21-Oct-2002 0	11250	15	11250	9172.4
571010 045701	INSPECT LEFT WING FRONT SPAR , WS 88.50 *CF				MTH HRS	21-Oct-2002 0	12000		12000	9922.4
571015 045701	INSPECT RIGHT WING FRONT SPAR, WS 88.50 *CF				MTH HRS	21-Oct-2002 0	12000		12000	9922.4
571020 045702	INSPECT LEFT WING MAIN SPAR, WS 61.50 *CF				MTH HRS	21-Oct-2002 0	12500		12500	10422.4
571025 045702	INSPECT RIGHT WING MAIN SPAR, WS 61.50 *CF				MTH HRS	21-Oct-2002 0	12500		12500	10422.4
571030 045703	INSPECT LEFT WING MAIN SPAR, WS 102.00 *CF				MTH HRS	21-Oct-2002 0	12000		12000	9922.4
571035 045703	INSPECT RIGHT WING MAIN SPAR, WS 102.00 *CF				MTH HRS	21-Oct-2002 0	12000		12000	9922.4
571040 045704	INSPECT LEFT WING MAIN SPAR, WS 154.00 *CF				MTH HRS	21-Oct-2002 0	12000		12000	9922.4
571045 045704	INSPECT RIGHT WING MAIN SPAR, WS 154.00 *CF				MTH HRS	21-Oct-2002 0	12000		12000	9922.4
571050 045705	INSPECT LEFT WING MAIN SPAR, WS 171.00 (INBOARD) *CF				MTH HRS	21-Oct-2002 0	13000		13000	10922.4
571055 045705	INSPECT RIGHT WING MAIN SPAR, WS 171.00 (INBOARD) *CF				MTH HRS	21-Oct-2002 0	13000		13000	10922.4
571060 045706	INSPECT LEFT WING REAR SPAR, WS 136.65 *CF				MTH HRS	21-Oct-2002 0	13000		13000	10922.4
571065 045706	INSPECT RIGHT WING REAR SPAR, WS 136.65 *CF				MTH HRS	21-Oct-2002 0	13000		13000	10922.4
571070 045707	INSPECT LEFT WING REAR SPAR, WS 154.00 *CF				MTH HRS	21-Oct-2002 0	13000		13000	10922.4

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Maintenance Inspections

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains	
571075 045707	INSPECT RIGHT WING REAR SPAR, WS 154.00 *CF				MTH HRS	21-Oct-2002 0				13000 13000	10922.4
571080 045708	INSPECT LEFT WING MAIN SPAR SPLICE, WS 111.00 *CF				MTH HRS	21-Oct-2002 0				12000 12000	9922.4
571085 045708	INSPECT RIGHT WING MAIN SPAR SPLICE, WS 111.00 *CF				MTH HRS	21-Oct-2002 0				12000 12000	9922.4
571090 045709	INSPECT LEFT WING REAR SPAR SPLICE, WS 111.00 *CF				MTH HRS	21-Oct-2002 0				12000 12000	9922.4
571095 045709	INSPECT RIGHT WING REAR SPAR SPLICE, WS 111.00 *CF				MTH HRS	21-Oct-2002 0				12000 12000	9922.4
571100 045710	INSPECT LEFT WING FRONT STRINGER SPLICE, WS 111.00 *CF				MTH HRS	21-Oct-2002 0				12000 12000	9922.4
571105 045710	INSPECT RIGHT WING FRONT STRINGER SPLICE, WS 111.00 *CF				MTH HRS	21-Oct-2002 0				12000 12000	9922.4
712085 047103	INSPECT LEFT ENGINE FORWARD ENGINE MOUNT AFT CHANNEL WEB *CF				MTH HRS	21-Oct-2002 0		15		15000 15000	12922.4
712090 047103	INSPECT RIGHT ENGINE FORWARD ENGINE MOUNT AFT CHANNEL WEB *CF				MTH HRS	21-Oct-2002 0		15		15000 15000	12922.4
712095 047104	INSPECT LEFT ENGINE FORWARD ENGINE MOUNT FORWARD CHANNEL WEB *CF				MTH HRS	21-Oct-2002 0		15		12000 12000	9922.4
712100 047104	INSPECT RIGHT ENGINE FORWARD ENGINE MOUNT FORWARD CHANNEL WEB *CF				MTH HRS	21-Oct-2002 0		15		12000 12000	9922.4
712105 047107	INSPECT LEFT ENGINE AFT ENGINE MOUNT *CF				MTH HRS	21-Oct-2002 0		15		15000 15000	12922.4
712110 047107	INSPECT RIGHT ENGINE AFT ENGINE MOUNT *CF				MTH HRS	21-Oct-2002 0		15		15000 15000	12922.4
714005 047101	INSPECT LEFT ENGINE FORWARD ENGINE BEAM AFT UPPER ANGLE COMMON TO AFT WEB, BL 34.90 *CF				MTH HRS	21-Oct-2002 0	8628			8628 8628	6550.4
714010 047101	INSPECT RIGHT ENGINE FORWARD ENGINE BEAM AFT UPPER ANGLE COMMON TO AFT WEB, BL 34.90 *CF				MTH HRS	21-Oct-2002 0	8628			8628 8628	6550.4
714015 047102	INSPECT LEFT ENGINE FORWARD ENGINE BEAM AFT WEB UPPER EDGE, BL 26.56 *CF				MTH HRS	21-Oct-2002 0	15000	15		15000 15000	12922.4
714020 047102	INSPECT RIGHT ENGINE FORWARD ENGINE BEAM AFT WEB UPPER EDGE, BL 26.56 *CF				MTH HRS	21-Oct-2002 0	15000	15		15000 15000	12922.4
714035 047105	INSPECT LEFT ENGINE FORWARD ENGINE BEAM AT ATTACHMENT TO FUSELAGE *CF				MTH HRS	21-Oct-2002 0	15000	15		15000 15000	12922.4
714040 047105	INSPECT RIGHT ENGINE FORWARD ENGINE BEAM AT ATTACHMENT TO FUSELAGE *CF				MTH HRS	21-Oct-2002 0	15000	15		15000 15000	12922.4
714045 047106	INSPECT LEFT ENGINE AFT ENGINE BEAM AT ATTACHMENT TO FUSELAGE *CF				MTH HRS	21-Oct-2002 0	15000	15		15000 15000	12922.4
714050 047106	INSPECT RIGHT ENGINE AFT ENGINE BEAM AT ATTACHMENT TO FUSELAGE *CF				MTH HRS	21-Oct-2002 0	15000	15		15000 15000	12922.4

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
211001 LEFT	PRESSURE SHUTOFF VALVE APA			5253-00-3 2395	MTH HRS	28-Aug-2008 1726	O/C	0		
211001 RIGHT	PRESSURE SHUTOFF VALVE APA			5253-00-3 2403	MTH HRS	28-Aug-2008 1726	O/C	0		
211002 LEFT	VARIABLE VALVE *CF			2601-21 0577	MTH	21-Oct-2002	O/C			
211002 RIGHT	VARIABLE VALVE *CF			2601-21 0583	MTH	21-Oct-2002	O/C			
211003	PRESSURE HEAT EXCHANGER *CF			10840A 735	MTH	21-Oct-2002	O/C			
211005	EMERGENCY PRESSURE SHUTOFF VALVE 9912422-2 *CF			2601-23 0312	MTH	21-Oct-2002	O/C			
212001	BAGGAGE COMPARTMENT BLOWER *CF			0113-12 0661	MTH	21-Oct-2002	O/C			
212003	(STO29) TEMPERATURE SWITCH *CF			1173T42-1 3247	MTH	21-Oct-2002	O/C			
212302	WINDSHIELD AIR BLOWER MOTOR			7003-200 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
213001	PRIMARY OUTFLOW VALVE 9912409-20 *CF			52771-316 816	MTH	21-Oct-2002	O/C			
213002	SECONDARY OUTFLOW VALVE 9912409-15 *CF B			52772-116 943	MTH	21-Oct-2002	O/C			
213003	PRESSURE CONTROLLER 9912409-13 *CF E			52770-116 1546	MTH	21-Oct-2002	O/C			
213005	DIFFERENTIAL PRESSURE INDICATOR 3001J73 *CF			C668511-0106 3337	MTH	21-Oct-2002	O/C			
213008	MANUAL PRESSURE SWITCH 9912409-4 *CF A			52773-001 1322	MTH	21-Oct-2002	O/C			
215000 AFT	EVAPORATOR BLOWER MOTOR *CF			1250211-24 NSN	MTH	21-Oct-2002	O/C			
215000 FORWARD	EVAPORATOR BLOWER MOTOR *CF			1260185-1 NSN	MTH	21-Oct-2002	O/C			
215001	FORWARD EVAPORATOR 9912583-9 *CF			1134300-3 241	MTH	21-Oct-2002	O/C			
215002	AFT EVAPORATOR 9912583-10			1134820-15 528	MTH ACH	19-Sep-2007 669	O/C	0		
215003	VAPOR CYCLE COMPRESSOR DRIVE MOTOR APA			1134146-1 008A	MTH ACH	02-Nov-2007 669	O/C	3000 0	3669	2823.3

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
215004	COMPRESSOR DRIVE 9912583-6	*CF		1134610-1 238		MTH 21-Oct-2002	O/C			
215005	CONDENSOR ASSEMBLY 9912583-7	APA		1134620-3 SN-UNKNOWN		MTH 29-Jun-2007 ACH 606	O/C	0		
215006	BINARY SWITCH	*CF		1250232-10 580		MTH 21-Oct-2002	O/C			
215007	RECEIVER DRYER ASSEMBLY 9912583-3	*CF		1134275-1 SN-UNKNOWN		MTH 21-Oct-2002	A/R			
215008	COMPRESSOR ASSEMBLY	*CF		1134130-5 183		MTH 21-Oct-2002	O/C			
215009	BLOWER CONDENSER	*CF		1250435-3 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
215010	AIR CONDITIONING FLIGHT HOURMETER	*CF		1250703-3 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
215011	COMPRESSOR DRIVE BELT			225L100 SN-UNKNOWN		MTH 02-Jan-2006 ACH 439	O/C	0		
215012	VAPOR CYCLE COMPRESSOR DRIVE MOTOR BRUSHES	APA		1251171 SN-UNKNOWN		MTH 02-Nov-2007 ACH 669	800	0	1469	623.3
216001	RAM AIR MODULATING VALVE	APA		27241287-15 5AH1E		MTH 11-Jun-2009 HRS 1921	O/C	0		
216002	TEMPERATURE CONTROLLER	*CF		1E58-7 3AV41		MTH 21-Oct-2002	O/C			
216003 AFT	(TC007) SENSOR 9912085-3	*CF		27221274 9AV454		MTH 21-Oct-2002	O/C			
216003 FORWARD	(UT006) SENSOR 9912085-3	*CF		27221274 8AV426		MTH 21-Oct-2002	O/C			
221002 AILERON	SERVO MOUNT	*CF	1	622-5735-021 108XP		MTH 21-Oct-2002	O/C			
221002 ELEVATOR	SERVO MOUNT	*CF	1	622-5735-022 10PDM		MTH 21-Oct-2002	O/C			
221002 RUDDER	SERVO MOUNT	*CF	1	622-5735-022 J245		MTH 21-Oct-2002	O/C			
221003 AILERON	SERVO SVO-3000	*CF	1	822-1168-002 109XX		MTH 21-Oct-2002	O/C			
221003 ELEVATOR	SERVO SVO-3000	*CF	1	822-1168-001 10NYF		MTH 21-Oct-2002	O/C			
221003 RUDDER	SERVO SVO-3000	*CF	1	822-1168-001 10BYY		MTH 21-Oct-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
221004	AUTOPILOT PANEL			622-6208-223 2NN7F	MTH HRS	25-Jun-2008 1688	O/C	0		
231001	RECEIVER-EXCITER KTR0953	CCS		064-01015-0001 33257	MTH HRS	29-Apr-2003 208	O/C	0		
231002	POWER AMP/ANTENNA COUPLER KAC-952	MCO		064-01017-0001 18314	MTH HRS	08-Oct-2003 353	O/C	0		
231003	MINIATURE-CONTROL ADAPTER KA-594	*CF	3	071-01268-0001 4668	MTH	21-Oct-2002	O/C			
231005	MINATURE CONTROL KFS-594	*CF	8	071-01274-0002 5265	MTH	21-Oct-2002	O/C			
231006 BOTTOM	VHF COMM 2 CONTROL		2.4	010-00418-11 24050319	MTH HRS	08-Jun-2007 1375	O/C	0		
231006 TOP	VHF COMM 1 CONTROL		2.4	010-00418-11 24050311	MTH HRS	08-Jun-2007 1375	O/C	0		
231007 BOTTOM	COMM 1 ANTENNA	*CF		17-40-02W 0526	MTH	21-Oct-2002	O/C			
231007 TOP	COMM 2 ANTENNA	TOL		VC10-126-1 0235	MTH HRS	28-Apr-2005 808	O/C	0		
235001 LEFT	AUDIO AMPLIFIER S3100-63	*CF	C	5636-1 901	MTH	21-Oct-2002	O/C			
235001 RIGHT	AUDIO AMPLIFIER S3100-63	FXE	C	5636-1 673	MTH HRS	16-Aug-2004 640	O/C	91		
237000	CVR UNDERWATER LOCATOR BEACON APA			DK120 DU9524	MTH HRS	28-Aug-2008 1726	O/C	0		
237000A	CVR LOCATOR BEACON BATTERY APA			810-2007/K 072014	MTH HRS	28-Aug-2008 1726	72	1	31-Jul-2014	52 m 9 d
237001	COCKPIT VOICE RECORDER *CF			2100-1020-02 0000183591	MTH	21-Oct-2002	O/C			
237002	CVR CONTROLLER	*CF	4	S251-1120-00 000182727	MTH	21-Oct-2002	O/C			
237003	CVR MICROPHONE	*CF		S055-0065-00 000178465	MTH	21-Oct-2002	O/C			
237004	CVR IMPACT SWITCH	*CF		6895D2-X-5-5 3993	MTH	21-Oct-2002	O/C			
243001	BATTERY TEMP INDICATOR			TS-C1A3 40002772	MTH HRS	14-Jan-2008 1602	O/C	0		
243003 LEFT	GENERATOR CONTROL UNIT *CF			51525-001F Y2312	MTH	21-Oct-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
243003 RIGHT	GENERATOR CONTROL UNIT	*CF		51525-001F Y2031		MTH 21-Oct-2002	O/C			
243004	BATTERY TEMP MONITOR	*CF		1529-1-1 3796		MTH 21-Oct-2002	O/C			
243006 LEFT	GENERATOR LOAD AMMETER	SWF		C662501-0107 C051111		MTH 21-Jun-2005 HRS 837	O/C	0		
243006 RIGHT	GENERATOR LOAD AMMETER	*CF		C662501-0107 E22819		MTH 21-Oct-2002	O/C			
243007	BATTERY S3597-4	APA		RG-380E/44LA2 40288075		MTH 15-Apr-2009 HRS 1891	O/C	0		
BATTERY SHOULD BE REPLACED EVERY 60 MONTHS OR 5000 HOURS PER CONCORDE BATTERY MANUAL.										
243008	BATTERY RELAY	*CF		A931F W23244		MTH 21-Oct-2002	O/C			
243011	DC POWER VOLTMETER	*CF		C662502-0101 E22816		MTH 21-Oct-2002	O/C			
245001 LEFT	START CONTROL P.C.B.	*CF		6318324-6 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
245001 RIGHT	START CONTROL P.C.B.	*CF		6318324-6 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
245002 LEFT	FUEL CONTROL P.C.B.	MCO		6318341-6 0331		MTH 06-Aug-2004 HRS 630	O/C	0		
245002 RIGHT	FUEL CONTROL P.C.B.	MCO		6318341-6 0336		MTH 06-Aug-2004 HRS 630	O/C	0		
245003 LEFT	IGNITOR CONTROL P.C.B.	*CF		6318322-3 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
245003 RIGHT	IGNITOR CONTROL P.C.B.	*CF		6318322-3 -		MTH 21-Oct-2002	O/C			
245004 LEFT	ANTI-ICE P.C.B.	*CF		6318343-6 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
245004 RIGHT	ANTI-ICE P.C.B.	*CF		6318343-6 -		MTH 21-Oct-2002	O/C			
245005 LEFT	PCB ATTENUATOR	*CF		6318346-1 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
245005 RIGHT	PCB ATTENUATOR	*CF		6318346-1 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
245006	ENVIRONMENTAL P.C.B.	*CF		6318356-2 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
245007	HYDRAULIC P.C.B.	*CF		6318344-1 SN-UNKNOWN		MTH 21-Oct-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
245008	TRIM RELAY P.C.B.	*CF		6518351-9 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
245009	DIMMING P.C.B.	*CF		6518353-4 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
245010	GEAR LOGIC 1 P.C.B.	*CF		6318345-1 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
245012	SPEEDBRAKE P.C.B.	*CF		6318347-1 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
245013 LEFT	IDLE CONTROL P.C.B.	*CF		6318348-11 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
245013 RIGHT	IDLE CONTROL P.C.B.	*CF		6318348-11 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
245014	GEAR LOGIC 2 P.C.B.	*CF		6318392-1 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
245015	GEAR MONITOR P.C.B.	*CF		6318394-1 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
245016	TAIL DEICE P.C.B	*CF		6318395-1 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
245020	OVERVOLTAGE DETECTOR	*CF		1645-1-3 3028	MTH	21-Oct-2002	O/C			
801101 LEFT ENGINE	STARTER GENERATOR 9912125-2	APA		300SGL129Q 6405XL2	MTH HRS	21-Oct-2009 1987	1000	0	2987	909.4
801101 RIGHT ENGINE	STARTER GENERATOR 9912125-2	APA		300SGL129Q 6818XL2	MTH HRS	21-Oct-2009 1987	1000	0	2987	909.4
256001	ELT TRANSMITTER C406-2	*CF		453-5000-999 02422	MTH	21-Oct-2002	O/C			
256002	ELT BEACON BATTERY PACK C406-2			452-0133 07012012	MTH HRS	28-Apr-2008 1651	60	10	30-Jun-2012	27 m 8 d
256003	REMOTE SWITCH	*CF		452-0010 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
256004	ELT ANTENNA	*CF		110-328-01 3082	MTH	21-Oct-2002	O/C			
256006 NO. 1	LIFE VEST	APA		P0201-105 980290	MTH HRS	01-May-2009 1898	60	0	31-May-2014	50 m 9 d
256006 NO. 2	LIFE VEST	APA		P0201-105 980259	MTH HRS	01-May-2009 1898	60	0	31-May-2014	50 m 9 d
256006 NO. 3	LIFE VEST	APA		P0201-105 980260	MTH HRS	01-May-2009 1898	60	0	31-May-2014	50 m 9 d

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
256006 NO. 4	LIFE VEST	APA		P0201-105 980295	MTH HRS	01-May-2009 1898	60	0	31-May-2014	50 m 9 d
256006 NO. 5	LIFE VEST	APA		P0201-105 980262	MTH HRS	01-May-2009 1898	60	0	31-May-2014	50 m 9 d
256006 NO. 6	LIFE VEST	APA		P0201-105 980261	MTH HRS	01-May-2009 1898	60	0	31-May-2014	50 m 9 d
256006 NO. 7	LIFE VEST	APA		P0201-105 980292	MTH HRS	01-May-2009 1898	60	0	31-May-2014	50 m 9 d
256006 NO. 8	LIFE VEST	APA		P0201-105 980294	MTH HRS	01-May-2009 1898	60	0	31-May-2014	50 m 9 d
256007	DIGITAL GPS INTERFACE UNIT *CF			453-6500 01506	MTH	21-Oct-2002	O/C			
261001 LEFT	FIRE DETECTOR SENSOR 9912416-1	*CF		3001-212-1004/455-9 204609	MTH	21-Oct-2002	O/C			
261001 RIGHT	FIRE DETECTOR SENSOR 9912416-1	*CF		3001-212-1004/455-9 204608	MTH	21-Oct-2002	O/C			
262001 LEFT ENGINE	FIRE EXTINGUISHER BOTTLE 9912048-6	*CF		30401102-2 48850B1	MTH	21-Oct-2002	O/C	0		
262001 RIGHT ENGINE	FIRE EXTINGUISHER BOTTLE 9912048-6	*CF		30401102-2 48852B1	MTH	21-Oct-2002	O/C	0		
262003 COCKPIT	PORTABLE FIRE EXTINGUISHER APA			C352TS X624295	MTH HRS	03-Nov-2008 1760	O/C	10		
262010 LEFT ENGINE NO.1 <i>262002 : L1</i>	FIRE EXTINGUISHER CARTRIDGE GNE			13083-5 04012012	MTH HRS	09-Feb-2007 1336	72	0	28-Feb-2013	35 m 6 d
262011 LEFT ENGINE NO.2 <i>262002 : L2</i>	FIRE EXTINGUISHER CARTRIDGE GNE			13083-5 04012012	MTH HRS	09-Feb-2007 1336	72	0	28-Feb-2013	35 m 6 d
262012 RIGHT ENGINE NO.1 <i>262002 : R1</i>	FIRE EXTINGUISHER CARTRIDGE GNE			13083-5 04012012	MTH HRS	09-Feb-2007 1336	72	0	28-Feb-2013	35 m 6 d
262013 RIGHT ENGINE NO.2 <i>262002 : R2</i>	FIRE EXTINGUISHER CARTRIDGE GNE			13083-5 04012012	MTH HRS	09-Feb-2007 1336	72	0	28-Feb-2013	35 m 6 d
272001	RUDDER BIAS VALVE	APA		5307-1 0289C	MTH HRS	20-Dec-2007 1590	O/C	0		
273001	SHAKER CONTROL	*CF	A	201 5600	MTH	21-Oct-2002	O/C			
273002	ELEVATOR TRIM SERVO	*CF		44430-3548 T738	MTH	21-Oct-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
275001	SHUTOFF VALVE	*CF		4083-1 256		MTH 21-Oct-2002	O/C			
275002 LEFT	FLAP ACTUATOR 9912365-5	*CF		1542000-7 1303		MTH 21-Oct-2002	O/C			
275002 RIGHT	FLAP ACTUATOR 9912365-5	*CF		1542000-7 1306		MTH 21-Oct-2002	O/C			
276001 LEFT	SPEED BRAKE ACTUATOR 9912375-4	*CF		1542100-5 1310		MTH 21-Oct-2002	O/C			
276001 RIGHT	SPEED BRAKE ACTUATOR 9912375-4	*CF		1542100-5 1287		MTH 21-Oct-2002	O/C			
281001 LEFT	SURGE TANK FLOAT VALVE 9912016-2	*CF		35C10D 2536		MTH 21-Oct-2002	O/C			
281001 RIGHT	SURGE TANK FLOAT VALVE 9912016-2	*CF		35C10D 2491		MTH 21-Oct-2002	O/C			
282001 LEFT	FUEL BOOST PUMP 9912017-4	*CF		1C7-13 5AV84		MTH 21-Oct-2002	O/C			
282001 RIGHT	FUEL BOOST PUMP 9912017-4	CCS		1C7-13 1AR10		MTH 19-Mar-2005 HRS 774	O/C	0		
282002 LEFT	EJECTOR FUEL AFT PUMP 9912190-2	*CF		RG45310 B8682		MTH 21-Oct-2002	O/C			
282002 RIGHT	EJECTOR FUEL AFT PUMP 9912190-2	*CF		RG45310 B8654		MTH 21-Oct-2002	O/C			
282003 LEFT	SOLENOID VALVE 9914470-3	*CF		527700-103 0240		MTH 21-Oct-2002	O/C			
282003 RIGHT	SOLENOID VALVE 9914470-3	*CF		527700-103 0241		MTH 21-Oct-2002	O/C			
282004 LEFT	FUEL MOTOR VALVE 9912014-3	*CF		EM9014-3 1292		MTH 21-Oct-2002	O/C			
282004 RIGHT	FUEL MOTOR VALVE 9912014-3	*CF		EM9014-3 1293		MTH 21-Oct-2002	O/C			
282005 LEFT	EJECTOR FUEL FORWARD PUMP 9912190-2	*CF		RG45310 B8683		MTH 21-Oct-2002	O/C			
282005 RIGHT	EJECTOR FUEL FORWARD PUMP 9912190-2	*CF		RG45310 B8672		MTH 21-Oct-2002	O/C			
282006	TRANSFER VALVE 9914103-6	*CF		ZSV57 204294		MTH 21-Oct-2002	O/C			
284001 LEFT	#5 FUEL PROBE 9912589-5	*CF		10664T05Y00 0739		MTH 21-Oct-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
284001 RIGHT	#5 FUEL PROBE 9912589-5	*CF		10664T05Y00 0737		MTH 21-Oct-2002	O/C			
284002 LEFT	#6 FUEL PROBE 9912589-6	*CF		10664T06Y00 0746		MTH 21-Oct-2002	O/C			
284002 RIGHT	#6 FUEL PROBE 9912589-6	*CF		10664T06Y00 0736		MTH 21-Oct-2002	O/C			
284003	FUEL QUANTITY SIGNAL CONDITIONER 9912589-9	*CF		10663B01Y02 02050625		MTH 21-Oct-2002	O/C			
284004 LEFT	#3 FUEL PROBE 9912589-3	*CF		10664T03Y00 0729		MTH 21-Oct-2002	O/C			
284004 RIGHT	#3 FUEL PROBE 9912589-3	*CF		10664T03Y00 0722		MTH 21-Oct-2002	O/C			
284005 LEFT	#4 INBOARD FUEL PROBE 9912589-4	SWF		10664T04Y00 0804		MTH 21-Jun-2005 HRS 837	O/C	0		
284005 RIGHT	#4 INBOARD FUEL PROBE 9912589-4	*CF		10664T04Y00 0987		MTH 21-Oct-2002	O/C			
284006 LEFT	#2 FUEL PROBE 9912589-2	*CF		10664T02Y00 0754		MTH 21-Oct-2002	O/C			
284006 RIGHT	#2 FUEL PROBE 9912589-2	*CF		10664T02Y00 0743		MTH 21-Oct-2002	O/C			
284007 LEFT	#1 FUEL PROBE 9912589-1	*CF		10664T01Y00 0755		MTH 21-Oct-2002	O/C			
284007 RIGHT	#1 FUEL PROBE 9912589-1	*CF		10664T01Y00 0754		MTH 21-Oct-2002	O/C			
284008 LEFT	FUEL LOW LEVEL SWITCH	*CF		L16H-9 SN-UNKNOWN		MTH 30-Oct-2002	O/C			
284008 RIGHT	FUEL LOW LEVEL SWITCH	*CF		L16H-9 SN-UNKNOWN		MTH 30-Oct-2002	O/C			
284009 LEFT	#4 OTBOARD FUEL PROBE 9912589-4	*CF		10664T04Y00 0993		MTH 21-Oct-2002	O/C			
284009 RIGHT	#4 OUTBOARD FUEL PROBE 9912589-4	*CF		10664T04Y00 0981		MTH 21-Oct-2002	O/C			
291002 LEFT	HYDRAULIC PUMP 9912062-6	*CF		24195-LAC 236		MTH 21-Oct-2002	O/C			
291002 RIGHT	HYDRAULIC PUMP 9912062-6	*CF		24195-LAC 242		MTH 21-Oct-2002	O/C			
291005	HYDRAULIC RESERVOIR ASSEMBLY	*CF		6317001-59 SN-UNKNOWN		MTH 21-Oct-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
291006	LOADING VALVE 9912423-39	MCO		4134-4 693	MTH HRS	03-May-2004 539	O/C	0		
291007	PRESSURE SWITCH GAUGE 9912373-4	APA		GPP1250-58 0803224	MTH HRS	11-Feb-2008 1620	O/C	0		
291008	HYDRAULIC MANIFOLD ASSY 9912423-40	*CF		8184-12 610	MTH	21-Oct-2002	O/C			
291009	RELIEF VALVE 9912423-38	MCO		2576-1 375	MTH HRS	03-May-2004 539	O/C	0		
291010 LEFT	SHUTOFF VALVE 9912400-4	*CF		AV24B1388-2 V24633	MTH	21-Oct-2002	O/C			
291010 RIGHT	SHUTOFF VALVE 9912400-4	*CF		AV24B1388-2 V24635	MTH	21-Oct-2002	O/C			
291011 LEFT	FLOW SWITCH VALVE 9912194-2	*CF		V10F14 680	MTH	21-Oct-2002	O/C			
291011 RIGHT	FLOW SWITCH VALVE 9912194-2	*CF		V10F14 647	MTH	21-Oct-2002	O/C			
291012	SPEEDBRAKE DUMP VALVE 9912423-33	*CF		4082-6 254	MTH	21-Oct-2002	O/C			
291014	GEAR VALVE 9912423-35	*CF		4051-3 251	MTH	21-Oct-2002	O/C			
291015	LANDING GEAR VALVE 9912423-36	*CF		9504-1 251	MTH	21-Oct-2002	O/C			
291016 LEFT	SPEEDBRAKE CHECK VALVE 9912423-31	*CF		9505-1 501	MTH	21-Oct-2002	O/C			
291016 RIGHT	SPEEDBRAKE CHECK VALVE 9912423-31	*CF		9505-1 502	MTH	21-Oct-2002	O/C			
291017	THERMAL RELIEF VALVE 9912423-32	*CF		2577-1 251	MTH	21-Oct-2002	O/C			
291018	PNEUMATIC DUMP VALVE 9912423-34	*CF		9503-2 254	MTH	21-Oct-2002	O/C			
291019 LEFT	ATTENUATOR VALVE 9912423-28	*CF		4107-3 251	MTH	21-Oct-2002	O/C			
291019 RIGHT	ATTENUATOR VALVE 9912423-27	*CF		4107-4 251	MTH	21-Oct-2002	O/C			
291020	SPEED BRAKE VALVE 9912423-30	*CF		4052-3 251	MTH	21-Oct-2002	O/C			
291021	FLAP VALVE 9912423-29	*CF		4052-4 256	MTH	21-Oct-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
301001	ISOLATION VALVE 9912403-2	ICT		2602-36 2021	MTH HRS	23-Jun-2008 1688	O/C	0		
301002 LEFT	PRESSURE SWITCH	*CF		1106P55-1 2099A	MTH	21-Oct-2002	O/C			
301002 RIGHT	PRESSURE SWITCH	*CF		1106P55-1 2164A	MTH	21-Oct-2002	O/C			
301003 LEFT	PRESS REGULATOR VALVE 9912495-5	*CF		1962-00-9 1493	MTH	21-Oct-2002	O/C			
301003 RIGHT	PRESS REGULATOR VALVE 9912495-5	*CF		1962-00-9 1495	MTH	21-Oct-2002	O/C			
301004 LEFT	TEMPERATURE SWITCH	*CF		1173T42-4 1954	MTH	21-Oct-2002	O/C			
301004 RIGHT	TEMPERATURE SWITCH	*CF		1173T42-4 1958	MTH	21-Oct-2002	O/C			
301005 LEFT	SOLENOID VALVE	*CF		3D2353-06 N19658	MTH	21-Oct-2002	O/C			
301005 RIGHT	SOLENOID VALVE	*CF		3D2353-06 N19688	MTH	21-Oct-2002	O/C			
301006 LEFT	HORIZONTAL STABILIZER BOOT	*CF		29S4D5244-15 MX42250	MTH	21-Oct-2002	O/C			
301006 RIGHT	HORIZONTAL STABILIZER BOOT	*CF		29S4D5244-16 MX42370	MTH	21-Oct-2002	O/C			
302001 LEFT	PRESS REG VALVE	*CF		5285-00-3 248	MTH	21-Oct-2002	O/C			
302001 RIGHT	PRESS REG VALVE	*CF		5285-00-3 258	MTH	21-Oct-2002	O/C			
302002 LEFT	INLET TEMP SWITCH	*CF		1173T0759 1753	MTH	21-Oct-2002	O/C			
302002 RIGHT	INLET TEMP SWITCH	*CF		1173T0759 1573	MTH	21-Oct-2002	O/C			
303002 LEFT	TUBE PITOT	*CF		PH502 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
303002 RIGHT	TUBE PITOT	*CF		PH502 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
304001	B/A TEMP MONITOR	*CF		1169-1 3302	MTH	21-Oct-2002	O/C			
304002	HEAT EXCHANGER 9912041-3	*CF		10653A 1368	MTH	21-Oct-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
304003	PRESSURE REGULATING CHECK VALVE 9912402-14	*CF		1962-00-3 1666		MTH 21-Oct-2002	O/C			
304004 AFT	FLOORBOARD TF006 SENSOR 9912085-3	*CF		27221274 5AU257		MTH 21-Oct-2002	O/C			
304004 FORWARD	T/C TT002 SENSOR 9912085-3	MCO		27221274 406		MTH 25-Mar-2003 HRS 157	O/C	0		
304005	TEMP CONTROLLER 9912085-6	*CF		1E58-1 3AV70		MTH 21-Oct-2002	O/C			
304006	TEMP CONTROL VALVE 9912085-1	*CF		27241287 5AV62		MTH 21-Oct-2002	O/C			
304007	ALCOHOL PUMP ASSY	*CF		476411E SN-UNKNOWN		MTH 21-Oct-2002	O/C			
304008 LEFT	W/S BLEED AIR VALVE BYLB50168	*CF		1403-25 3062		MTH 21-Oct-2002	O/C			
304008 RIGHT	W/S BLEED AIR VALVE BYLB50168	*CF		1403-25 2989		MTH 21-Oct-2002	O/C			
304009	PRESSURE SWITCH	*CF		1115P25 3814AB		MTH 21-Oct-2002	O/C			
304010 LEFT	PITOT STATIC CURRENT SENSOR	*CF		76250-1 4845		MTH 21-Oct-2002	O/C			
304010 RIGHT	PITOT STATIC CURRENT SENSOR	*CF		76250-1 4811		MTH 21-Oct-2002	O/C			
304013 LEFT	PITOT STATIC CURRENT SENSOR	*CF		76250-1 NSN		MTH 21-Oct-2002	O/C			
304013 RIGHT	PITOT STATIC CURRENT SENSOR	*CF		76250-1 NSN		MTH 21-Oct-2002	O/C			
312001 LEFT	DIGITAL CLOCK	TOL		M877A5V 15026		MTH 28-Apr-2005 HRS 808	O/C	152		
312001 RIGHT	DIGITAL CLOCK	TOL		M877A5V 13714		MTH 28-Apr-2005 HRS 808	O/C	656		
313001	FLIGHT HOUR METER 85071	*CF		C664503-0104 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
315001	CABIN ALT SWITCH 9910095-6	*CF		GB300NA161 0219169		MTH 21-Oct-2002	O/C			
315002	MASTER ANNUNCIATOR 9912586-2	SWF		9912586-2 586000124		MTH 21-Jun-2005 HRS 837	O/C	0		
321001 LEFT MAIN	(AND ATTACHING HARDWARE) LANDING GEAR	*CF		6341200-7 41		MTH 21-Oct-2002	N/R			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
321001 RIGHT MAIN	(AND ATTACHING HARDWARE) LANDING GEAR	*CF		6341200-8 39	MTH	21-Oct-2002	N/R			
321003 LEFT MAIN GEAR	TRUNNION	*CF		6341221-5 SN-UNKNOWN	MTH LDG	21-Oct-2002 0	39991	0	39991	38771
321003 RIGHT MAIN GEAR <i>321004 : R</i>	TRUNNION	*CF		6341221-6 SN-UNKNOWN	MTH LDG	21-Oct-2002 0	39991	0	39991	38771
321004	FORK PISTON ASSEMBLY	*CF		6342200-4 SN-UNKNOWN	MTH LDG	21-Oct-2002 0	12500	0	12500	11280
321005 LEFT MAIN GEAR	OLEO ASSEMBLY RUSSIAN OR DUTCH	APA		6341201-1 238	MTH HRS LDG	17-Nov-2008 1770 1062	28075	1057	28080	26860
321005 RIGHT MAIN GEAR	OLEO ASSEMBLY RUSSIAN OR DUTCH300 & ON	MCO		6341201-1 307	MTH HRS LDG	26-Aug-2003 321 173	28075	63	28185	26965
321007 LEFT	TRAILING LINK AND AXLE ASSEMBLY	*CF		6341241-1 NSN	MTH LDG	21-Oct-2002 0	41666	0	41666	40446
321007 RIGHT	TRAILING LINK AND AXLE ASSEMBLY	*CF		6341241-2 NSN	MTH LDG	21-Oct-2002 0	41666	0	41666	40446
321011 LEFT MAIN GEAR	OLEO ASSEMBLY LOWER BARREL RUSSIAN OR DUTCH	*CF		6341135-3 NSN	MTH LDG	21-Oct-2002 0	16224	0	16224	15004
321011 RIGHT MAIN GEAR	OLEO ASSEMBLY LOWER BARREL	*CF		6341135-3 NSN	MTH LDG	21-Oct-2002 0	16224	0	16224	15004
321012 LEFT MAIN GEAR	OLEO ASSEMBLY UPPER BEARING ASSEMBLY RUSSIAN OR DUTCH	*CF		6341133-9 NSN	MTH LDG	21-Oct-2002 0	19713	0	19713	18493
321012 RIGHT MAIN GEAR	OLEO ASSEMBLY UPPER BEARING ASSEMBLY RUSSIAN OR DUTCH	*CF		6341133-9 NSN	MTH LDG	21-Oct-2002 0	19713	0	19713	18493
322001	NOSE LANDING GEAR SHIMMY DAMPER	MCO		6343001-9 1419X	MTH HRS LDG	26-Aug-2003 321 173	O/C	0		
322002	NOSE LANDING GEAR (AND ATTACHING HARDWARE) ASSEMBLY	*CF		6342200-3 106	MTH LDG	21-Oct-2002 0	22500	0	22500	21280
322005	NOSE LANDING GEAR ASSEMBLY	*CF		6342200-2 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
323001 LEFT MAIN GEAR	SIDE BRACE ACTUATOR 9912573-2	*CF		1556700-3 0250	MTH LDG	21-Oct-2002 0	41666	0	41666	40446
323001 RIGHT MAIN GEAR	SIDE BRACE ACTUATOR 9912573-2	*CF		1556700-3 0254	MTH LDG	21-Oct-2002 0	41666	0	41666	40446
323002 LEFT MAIN GEAR	UPLOCK	APA		6327504-6 465	MTH HRS LDG	08-Nov-2007 1538 942	O/C	942		
323002 RIGHT MAIN GEAR	UPLOCK	APA		6327504-6 445	MTH HRS LDG	08-Nov-2007 1538 942	O/C	942		

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
323004	NOSE GEAR ACTUATOR ASSEMBLY 9912370-4	*CF		1541900-5 0668	MTH LDG	21-Oct-2002 0	12000	0	12000	10780
323005	NOSE LANDING GEAR UPLOCK ACTUATOR *CF			6327504-7 115	MTH	21-Oct-2002	O/C			
323006	HYDRAULIC SHUTTLE VALVE *CF			98312 0257	MTH	21-Oct-2002	O/C			
323020	PNEUMATIC BLOWDOWN/EMERGENCY BRAKE BOTTLE 9912368-2	*CF		40005320-2 3577	MTH	21-Oct-2002	288	4	30-Jun-2026	195 m 8 d
323021	EMERGENCY GEAR BOTTLE GAUGE *CF			18225901 016034	MTH	21-Oct-2002	O/C			
324001 LEFT MAIN GEAR	WHEEL ASSEMBLY 9912743-4	APA		3-1601-2 0351	MTH HRS LDG	12-Dec-2008 1782 1067	O/C			1067
324001 RIGHT MAIN GEAR	WHEEL ASSEMBLY 9912743-4	APA		3-1601-2 0356	MTH HRS LDG	12-Dec-2008 1782 1067	O/C			1067
324002 NOSE LANDING GEAR	WHEEL ASSEMBLY *CF	ICT		3-1418OPT-4 5553	MTH HRS LDG	24-Feb-2010 2059.3 1210	O/C			1210
324003 LEFT MAIN GEAR	TIRE 9912576-1	APA		026-528-0 8176W00656	MTH HRS LDG	12-Dec-2008 1782 1067	O/C			0
324003 RIGHT MAIN GEAR	TIRE 9912576-1	APA		026-528-0 8180W00609	MTH HRS LDG	12-Dec-2008 1782 1067	O/C			0
324004	NOSE LANDING GEAR TIRE *CF	ICT		030-611-0 8286W00229	MTH HRS LDG	24-Feb-2010 2059.3 1210	O/C			0 0 0
324005 LEFT MAIN GEAR	BRAKE ASSEMBLY 9912743-5	APA		2-1651-1 0712	MTH HRS LDG	20-Feb-2009 1839 1091	O/C			0
324005 RIGHT MAIN GEAR	BRAKE ASSEMBLY 9912743-5	APA		2-1651-1 0047	MTH HRS LDG	20-Sep-2007 1489 916	O/C			0
324101	BRAKE ANTISKID VALVE 9912575-4	*CF		38-861-1 249	MTH	21-Oct-2002	O/C			
324102 LEFT	ANTISKID TRANSDUCER 9912305-2	*CF		40-955 6089	MTH	21-Oct-2002	O/C			
324102 RIGHT	ANTISKID TRANSDUCER 9912305-2	*CF		40-955 6078	MTH	21-Oct-2002	O/C			
324103	DIGITAL BOX 9912575-3	*CF		142-031-1 187	MTH	21-Oct-2002	O/C			
324104	BRAKE PRESSURE SWITCH *CF			GPP1250-77 0209056	MTH	21-Oct-2002	O/C			
324105	PARKING BRAKE VALVE 9912388-1	*CF		95853 0784A	MTH	21-Oct-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
324106	HYDRAULIC PUMP MOTOR 9912373-1	*CF		MP50B1 2375		MTH 21-Oct-2002	O/C			
324107	BRAKE ANTISKID ACCUMULATOR 9912373-1	*CF		57C57663 0631		MTH 21-Oct-2002	O/C			
324108	LOW PRESSURE SWITCH 9912373-1	*CF		GPP1250-29 0219669		MTH 21-Oct-2002	O/C			
324109	BRAKE PRESSURE PUMP 9912364-2	*CF		640929 1533		MTH 21-Oct-2002	O/C			
324110	EMERGENCY BRAKE VALVE 9912387-3	*CF		878208-03 V265		MTH 21-Oct-2002	O/C			
324111	FAULT DISPLAY UNIT 9912305-9	*CF		42-92750 1097A		MTH 21-Oct-2002	O/C			
324113	RELIEF VALVE	*CF		1785-1 579		MTH 21-Oct-2002	O/C			
326001 LEFT MAIN GEAR	UNLOCK SWITCH	*CF		65-430087 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
326001 NOSE LANDING GEAR	UNLOCK SWITCH	*CF		65-430087 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
326001 RIGHT MAIN GEAR	UNLOCK SWITCH	*CF		65-430087 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
331001 CENTER	LIGHT DIMMER	*CF		273-1 0215124		MTH 21-Oct-2002	O/C			
331001 LEFT	LIGHT DIMMER	*CF		273-1 0218042		MTH 21-Oct-2002	O/C			
331001 RIGHT	LIGHT DIMMER	*CF		273-1 0214182		MTH 21-Oct-2002	O/C			
331002	ELECTRICAL PANEL INVERTER *CF			EM2044-1 3820A		MTH 21-Oct-2002	O/C			
332001 AFT	STATIC INVERTER 500VA --			SS50 388		MTH 10-Aug-2007 HRS 1439	O/C	0		
332001 L1	FORWARD LEFT INVERTER *CF			AL750PS SN-UNKNOWN		MTH 21-Oct-2002	O/C			
332001 L2	MID FORWARD INVERTER *CF			AL750PS SN-UNKNOWN		MTH 21-Oct-2002	O/C			
332001 L3	MID LEFT INVERTER *CF			AL750PS SN-UNKNOWN		MTH 21-Oct-2002	O/C			
332001 L4	AFT MID INVERTER *CF			AL750PS SN-UNKNOWN		MTH 21-Oct-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
332001 L5	AFT LEFT INVERTER	*CF		AL750PS SN-UNKNOWN		MTH 21-Oct-2002	O/C			
332001 R1	FORWARD RIGHT INVERTER	*CF		AL750PS SN-UNKNOWN		MTH 21-Oct-2002	O/C			
332001 R2	MID FORWARD INVERTER	*CF		AL750PS SN-UNKNOWN		MTH 21-Oct-2002	O/C			
332001 R3	MID RIGHT INVERTER	*CF		AL750PS SN-UNKNOWN		MTH 21-Oct-2002	O/C			
332001 R4	AFT MID INVERTER	*CF		AL750PS SN-UNKNOWN		MTH 21-Oct-2002	O/C			
332001 R5	AFT RIGHT INVERTER	*CF		AL750PS SN-UNKNOWN		MTH 21-Oct-2002	O/C			
334001	GROUND RECEPTACLE LIGHT			90033-13 014674		MTH 08-Apr-2006 HRS 1173	O/C	0		
334003 LEFT	COLLISION LIGHT POWER SUPPLY	*CF	1	04-1502-1408 18437		MTH 21-Oct-2002	O/C			
334003 RIGHT	COLLISION LIGHT POWER SUPPLY	*CF	1	04-1502-1408 18441		MTH 21-Oct-2002	O/C			
334004 LEFT	LANDING LAMP HOUSING	*CF		50033025-1 1258		MTH 21-Oct-2002	O/C			
334004 RIGHT	LANDING LAMP HOUSING	*CF		50033025-1 1250		MTH 21-Oct-2002	O/C			
334005 LEFT	COLLISION LIGHT ASSEMBLY	*CF	1	03-1302-0003 18797		MTH 21-Oct-2002	O/C			
334005 RIGHT	COLLISION LIGHT ASSEMBLY	*CF	1	03-1302-0004 17149		MTH 21-Oct-2002	O/C			
335000 LEFT	EMERGENCY EXIT LIGHT BATTERY	*CF		CBS28 1048		MTH 21-Oct-2002	O/C	0		
341001 LEFT	AIR DATA COMPUTER ADC-3000			822-1109-004 1416C		MTH 02-Apr-2005 HRS 789	O/C	0		
341001 RIGHT	AIR DATA COMPUTER ADC-3000	MCO		822-1109-004 NKXJ		MTH 06-Aug-2004 HRS 630	O/C	0		
341002 STANDBY	ALTIMETER/AIRSPEED INDICATOR	*CF	11	WL102AMS6 AN945		MTH 21-Oct-2002	O/C			
341006	AOA INDICATOR	*CF		C12405-1 581		MTH 21-Oct-2002	O/C			
341007	AOA SENSOR	*CF		C-12717-1 1002		MTH 21-Oct-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
341008	BAROMETRIC SWITCH	*CF		GBC300-156 0223133		MTH 21-Oct-2002	O/C			
341010 AFT	RADIO ALT ANTENNA	*CF		S67-2002 25281		MTH 21-Oct-2002	O/C			
341010 FORWARD	RADIO ALT ANTENNA	*CF		S67-2002 25282		MTH 21-Oct-2002	O/C			
341011	RADIO ALTIMETER TRANSMITTER ALT-55	*CF	11	622-2855-011 10J3V		MTH 21-Oct-2002	O/C			
341012	RADIO ALT CONVERTER	MCO		622-7209-003 467		MTH 06-Aug-2004 HRS 630	O/C	0		
341030	TEMPERATURE PROBE SENSOR	*CF		0129G A43854		MTH 21-Oct-2002	O/C			
341101	IAPS CARD CAGE ICC-3001	*CF		822-1459-001 10N8W		MTH 21-Oct-2002	O/C			
341102 LEFT	IO PROCESSOR CARD ICO-3000	*CF		822-1130-151 10J7Y		MTH 21-Oct-2002	O/C			
341102 RIGHT	IO PROCESSOR CARD IOC-3000	*CF		822-1130-151 10GMX		MTH 21-Oct-2002	O/C			
341103 NO. 1	CONFIGURATION CONTROL STRAPPING UNIT	*CF		822-1363-002 107LN		MTH 21-Oct-2002	O/C			
341103 NO. 2	CONFIGURATION CONTROL STRAPPING UNIT	*CF		822-1363-002 107LP		MTH 21-Oct-2002	O/C			
342002 LEFT	AHRS COMPUTER AHC-3000	MCO		822-1110-002 1BVYD		MTH 06-Aug-2004 HRS 630	O/C	0		
342002 RIGHT	AHRS COMPUTER AHC-3000	*CF	1	822-1110-002 1044Y		MTH 21-Oct-2002	O/C			
342003	STANDBY HSI INDICATOR S3100-303	APA		2855-01-1 296		MTH 29-Jun-2007 HRS 1390	O/C	2084		
342005 LEFT	FLIGHT GUIDANCE COMPUTER FGC-3000	*CF	1	822-1108-122 10CCF		MTH 21-Oct-2002	O/C			
342005 RIGHT	FLIGHT GUIDANCE COMPUTER FGC-3000	*CF	1	822-1108-122 10F9N		MTH 21-Oct-2002	O/C			
342006 LEFT	FLUX DETECTION UNIT FDU-3000	*CF		822-1193-001 27340		MTH 21-Oct-2002	O/C			
342006 RIGHT	FLUX DETECTION UNIT FDU-3000	*CF		822-1193-001 27243		MTH 21-Oct-2002	O/C			
342007 LEFT	EXTERNAL COMPENSATION UNIT ECU-3000	*CF		822-1200-001 10F1D		MTH 21-Oct-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
342007 RIGHT	EXTERNAL COMPENSATION UNIT ECU-3000	*CF		822-1200-003 10FIT		MTH 21-Oct-2002	O/C			
342008 LEFT	IAPS POWER SUPPLY PWR-3000	*CF	6	822-1137-001 HKYN		MTH 21-Oct-2002	O/C			
342008 RIGHT	IAPS POWER SUPPLY PWR-3000	*CF	6	822-1137-001 HLOJ		MTH 21-Oct-2002	O/C			
342009	ENVIROMENTAL CONTROL IEC-3001	*CF		822-1167-001 10LGN		MTH 21-Oct-2002	O/C			
342010 LEFT	OPERATION CONFIGURATION MODULE OCM-3100	*CF		822-1484-201 10NOW		MTH 21-Oct-2002	O/C			
342010 RIGHT	OPERATION CONFIGURATION MODULE OCM-3100	*CF		822-1484-201 10NOV		MTH 21-Oct-2002	O/C			
342030	STANDBY GYRO AI-300AE	ICT	3	501-1568-56 5083		MTH 29-Oct-2002 HRS 18	O/C	0		
342031	STANDBY GYRO POWER SUPPLY PS-834	APA		501-1682-01 1799		MTH 01-May-2009 HRS 1898	O/C	1898		
342301 LEFT	MODE SELECTOR MSP-85	*CF	10	622-6209-019 10DVH		MTH 21-Oct-2002	O/C			
342301 RIGHT	MODE SELECTOR MSP-85	*CF	10	622-6209-019 10J9C		MTH 21-Oct-2002	O/C			
342302 CENTER	ADAPTIVE FLT DISPLAY	*CF	12	822-1084-206 1069F		MTH 21-Oct-2002	O/C			
342302 LEFT	ADAPTIVE FLT DISPLAY	*CF	12	822-1084-206 12GDB		MTH 21-Oct-2002	O/C			
342302 RIGHT	MULTI-FUNCTION FLT DISPLAY	*CF	12	822-1084-206 NRWG		MTH 21-Oct-2002	O/C			
342303	COURSE PANEL CKP-3000	*CF		822-1281-002 10DRY		MTH 21-Oct-2002	O/C			
342304 LEFT	DISPLAY CONTROL PANEL DCP-3000	*CF	B	822-1134-102 10FNR		MTH 21-Oct-2002	O/C			
342304 RIGHT	DISPLAY CONTROL PANEL DCP-3000	*CF	B	822-1134-102 10HHC		MTH 21-Oct-2002	O/C			
343000	MARKER BEACON RECEIVER KMR-675	*CF	1	066-01044-0001 1734		MTH 21-Oct-2002	O/C			
343001	MARKER BEACON ANTENNA	*CF		31-10-01 4291		MTH 21-Oct-2002	O/C			
343002	DUAL GLIDESCOPE COUPLER	*CF		82-70-01 1307		MTH 21-Oct-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
343003	GLIDESCOPE ANTENNA	*CF		RGS10-48 A8511		MTH 21-Oct-2002	O/C			
344001	EGPWS COMPUTER MARK(V111)HONEYW ELL	MCO		965-1206-004 1477		MTH 27-Nov-2002 HRS 64	O/C	0		
344002	RADAR TRANSCEIVER RTA-800	*CF		822-1050-004 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
344011	STORMSCOPE PROCESSOR	MCO		78-8060-6086-3 80147		MTH 26-Aug-2003 HRS 321	O/C	0		
344012	STORMSCOPE ANTENNA WX-1000E	ICT		78-8051-9200-8 81609		MTH 26-May-2007 HRS 1373	O/C	0		
345001 FORWARD	DME 1 ANTENNA	*CF		56-80-01 8212		MTH 21-Oct-2002	O/C			
345002 LEFT	DME 1 TRANSCEIVER KN-63	MKE		066-01070-0001 X15921		MTH 10-Nov-2005 HRS 979	O/C	0		
345003 LEFT	DME INDICATOR KDI-574	*CF		066-01069-0014 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
345004 LEFT	DME CONVERTER KDA-689	*CF	1	071-01227-0001 11059		MTH 21-Oct-2002	O/C			
345005 LEFT	NAVIGATION ANTENNA C598505-0303	*CF		22-37-101 2959		MTH 21-Oct-2002	O/C			
345005 RIGHT	NAVIGATION ANTENNA C598505-0303	*CF		22-37-101 2962		MTH 21-Oct-2002	O/C			
345007	DUAL NAV CONVERTER KN-40 S3100-19	*CF	8	066-01130-0701 12241		MTH 21-Oct-2002	O/C			
345020 TOP	ADF 1 ANTENNA KA-44B	*CF		071-01234-0002 77818		MTH 21-Oct-2002	O/C			
345021	ADF 1 RECEIVER KR-87	*CF		066-01072-0006 76606		MTH 21-Oct-2002	O/C			
345040 AFT	TRANSPONDER 2 ANTENNA 85226	*CF		DMNI50-2-2 84241		MTH 21-Oct-2002	O/C			
345040 FORWARD	TRANSPONDER 1 ANTENNA 85226	*CF		DMNI50-2-2 84083		MTH 21-Oct-2002	O/C			
345041 NO. 1	TRANSPONDER GARMIN		4.06	010-00230-21 84306526		MTH 08-Jun-2007 HRS 1375	O/C	0		
345041 NO. 2	TRANSPONDER GARMIN		4.06	010-00230-21 84306521		MTH 08-Jun-2007 HRS 1375	O/C	0		
345049	FMS NAV COMPUTER S3100-302/UNS1L	APA		2116-42-1110 184		MTH 09-Jan-2009 HRS 1809	O/C	0		

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
345050	GPS FMS DISPLAY S3100-241	*CF	8	1117-1-104 3263		MTH 21-Oct-2002	O/C			
345051 NO. 1	GPS FMS ANTENNA	APA		10706 14020		MTH 09-Jan-2009 HRS 1809	O/C	0		
345052	FMS CONFIGURATION MODULE *CF			11921 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
345055	SATELITE DATA LINK TRANSCEIVER			010-00339-01 47757751		MTH 08-Jun-2007 HRS 1375	O/C	0		
345062 BOTTOM	TCAS ANTENNA	*CF		805-10003-001 80146		MTH 21-Oct-2002	O/C			
345063	HP SKYWATCH PROCESSOR TRC-899	*CF		805-11900-001 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
345068 NO. 2	CONTROL AUDIO PANEL	TOL	1	822-1861-030 293GL		MTH 28-Apr-2005 HRS 808	O/C	0		
346050	E.L. PANEL 9912596-25			95-149-25 N/A		MTH 08-Jun-2007 HRS 1375	O/C	0		
350006	OXYGEN CYLINDER PURITAN/DOT-E8162-1 850	*CF		176274-50 10070		MTH 21-Oct-2002	180	7	31-Mar-2017	84 m 9 d
350007	OXYGEN PRESSURE GAUGE MD-97	*CF		C668512-0101 E22827		MTH 21-Oct-2002	O/C			
351002 COPILOT	OXYGEN MASK 9914067-41	APA		MC10-16-101 96342		MTH 03-Nov-2008 HRS 1760	72	0	30-Nov-2014	56 m 8 d
351002 PILOT	OXYGEN MASK 9914067-41	APA		MC10-16-101 98929		MTH 03-Nov-2008 HRS 1760	72	0	30-Nov-2014	56 m 8 d
351003	OXYGEN PRESSURE SWITCH *CF			P24032 0563		MTH 21-Oct-2002	O/C			
361001 LEFT	PRECOOL TEMPERATURE SENSOR 9912584-3	APA		27431501-10 1BD27		MTH 28-Aug-2008 HRS 1726	O/C	0		
361001 RIGHT	PRECOOL TEMPERATURE SENSOR 9912584-3	APA		27431501-10 1BD32		MTH 28-Aug-2008 HRS 1726	O/C	0		
361002 LEFT	B/A PRECOOLER ASSEMBLY 9914402-4	*CF		8161-2 S4883T0255		MTH 21-Oct-2002	O/C			
361002 RIGHT	B/A PRECOOLER ASSEMBLY 9914402-4	*CF		8161-2 S4883T0260		MTH 21-Oct-2002	O/C			
361003 LEFT	MODULATING VALVE 9912584-1	*CF		1H139-1 5AV45		MTH 21-Oct-2002	O/C			
361003 RIGHT	MODULATING VALVE 9912584-2	*CF		1H139-2 5AV36		MTH 21-Oct-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
361005	PRESSURE SWITCH	*CF		P18M30 2997	MTH	21-Oct-2002	O/C			
361006 LEFT	OVERTEMPERATURE SWITCH 9914149-2	*CF		1173T181-2 3377	MTH	21-Oct-2002	O/C			
361006 RIGHT	OVERTEMPERATURE SWITCH 9914149-2	*CF		1173T181-2 3553	MTH	21-Oct-2002	O/C			
361007	B/A PRESSURE REGULATOR 9912510-1	APA		1H75-18 1AV3	MTH HRS	10-Sep-2008 1732	O/C	0		
522001	INFLATABLE DOOR SEAL 9912075-4	*CF		S15501-4 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
530000	RADOME ASSEMBLY	*CF		6313101-47-1 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
531000 LEFT	TRUNNION SUPPORT FITTING *CF	*CF		5513056-5 SN-UNKNOWN	MTH LDG	21-Oct-2002 0	22500	0	22500	21280
531000 RIGHT	TRUNNION SUPPORT FITTING *CF	*CF		5513056-6 SN-UNKNOWN	MTH LDG	21-Oct-2002 0	22500	0	22500	21280
531001	NOSE LANDING GEAR ACTUATOR FITTING RUSSIAN	*CF		6511105-1 SN-UNKNOWN	MTH LDG	21-Oct-2002 0	23900	0	23900	22680
561001 LEFT	WINDSHIELD 9912064-15	*CF		P00042-1 308	MTH	21-Oct-2002	O/C			
561001 RIGHT	WINDSHIELD 9912064-16	*CF		P00042-2 389	MTH	21-Oct-2002	O/C			
561002 L1	CABIN DOOR WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
561002 L2	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
561002 L3	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
561002 L4	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
561002 L5	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
561002 L6	CABIN DOOR WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
561002 R1	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
561002 R2	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN	MTH	21-Oct-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
561002 R3	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
561002 R4	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
561002 R5	CABIN WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
561002 R6	CABIN DOOR WINDOW 9912207-8	*CF		161100-03 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
561003 LEFT	PILOT SIDE WINDOW	*CF		6311263-1 0119		MTH 21-Oct-2002	O/C			
561004 RIGHT	CO-PILOT SIDE WINDOW	*CF		6311263-2 0180		MTH 21-Oct-2002	O/C			
571000 LEFT	AFT TRUNNION ATTACH FITTING RUSSIAN OR DUTCH300 & ON	*CF		6321070-9 SN-UNKNOWN		MTH 21-Oct-2002 LDG 0	20480	0	20480	19260
571000 RIGHT	AFT TRUNNION ATTACH FITTING RUSSIAN OR DUTCH300 & ON	*CF		6321070-10 SN-UNKNOWN		MTH 21-Oct-2002 LDG 0	20480	0	20480	19260
571001 LEFT	FORWARD TRUNNION ATTACH FITTING RUSSIAN OR DUTCH300 & ON	*CF		6321060-9 SN-UNKNOWN		MTH 21-Oct-2002 LDG 0	20480	0	20480	19260
571001 RIGHT	FORWARD TRUNNION ATTACH FITTING	*CF		6321060-10 SN-UNKNOWN		MTH 21-Oct-2002 LDG 0	20480	0	20480	19260
571002 LEFT	SIDE BRACE FITTING	*CF		6321080-1 SN-UNKNOWN		MTH 21-Oct-2002 LDG 0	35000	0	35000	33780
571002 RIGHT	SIDE BRACE FITTING RUSSIAN OR DUTCH300 & ON	*CF		6321080-2 SN-UNKNOWN		MTH 21-Oct-2002 LDG 0	35000	0	35000	33780
712001 LEFT ENGINE FORWARD BOTTOM	ISOLATOR MOUNT 9912410-3	*CF		LM601SA5 3113		MTH 21-Oct-2002 HRS 0	3500	0	3500	1422.4
712001 LEFT ENGINE FORWARD TOP	ISOLATOR MOUNT 9912410-3	*CF		LM601SA5 3164		MTH 21-Oct-2002 HRS 0	3500	0	3500	1422.4
712001 RIGHT ENGINE FORWARD BOTTOM	ISOLATOR MOUNT 9912410-3	*CF		LM601SA5 3130		MTH 21-Oct-2002 HRS 0	3500	0	3500	1422.4
712001 RIGHT ENGINE FORWARD TOP	ISOLATOR MOUNT 9912410-3	*CF		LM601SA5 3146		MTH 21-Oct-2002 HRS 0	3500	0	3500	1422.4
712002 LEFT ENGINE	AFT ISOLATOR MOUNT 9912410-2	*CF		LM601SA4 SN-UNKNOWN		MTH 21-Oct-2002 HRS 0	3500	0	3500	1422.4
712002 RIGHT ENGINE	AFT ISOLATOR MOUNT 9912410-2	*CF		LM601SA4 SN-UNKNOWN		MTH 21-Oct-2002 HRS 0	3500	0	3500	1422.4

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
71EN1 NO. 1 <i>710001 : E1**L</i>	ENGINE FJ44-2C	ICT		60500 126095	MTH HRS	19-Jun-2008 1688	E/C 1688	1688		
71EN2 NO. 2 <i>710001 : E2**R</i>	ENGINE FJ44-2C	ICT		60500 126094	MTH HRS	19-Jun-2008 1688	E/C 1688	1688		
720001 E1	FAN ROTOR	ICT		65502 AU00144	MTH HRS LDG	19-Jun-2008 1688 1115	6000	921	6194	4974
720001 E2	FAN ROTOR	ICT		65502 AU00120	MTH HRS LDG	19-Jun-2008 1688 1133	6000	903	6230	5010
720002 E1	IP COMPRESSOR ROTOR	ICT		61968 AU01442	MTH HRS LDG	19-Jun-2008 1688 1115	8000	921	8194	6974
720002 E2	IP COMPRESSOR ROTOR	ICT		61968 AU01462	MTH HRS LDG	19-Jun-2008 1688 1133	8000	903	8230	7010
720003 E1	COMPLETE LP SHAFT ASSEMBLY	ICT		64257 RX1SN10737	MTH HRS	19-Jun-2008 1688	O/C	1688		
720003 E2	COMPLETE LP SHAFT ASSEMBLY	ICT		64257 RX1SN10736	MTH HRS	19-Jun-2008 1688	O/C	1688		
720004 E1	HIGH PRESSURE SHAFT	ICT		64711 AU00731	MTH HRS	19-Jun-2008 1688	O/C	1688		
720004 E2	HIGH PRESSURE SHAFT	ICT		64711 AU00730	MTH HRS	19-Jun-2008 1688	O/C	1688		
720005 E1	HP COMPRESSOR COVER	ICT		65593 AU01878	MTH HRS	19-Jun-2008 1688	O/C	1688		
720005 E2	HP COMPRESSOR COVER	ICT		65593 AU01794	MTH HRS	19-Jun-2008 1688	O/C	1688		
720006 E1	DIFFUSER CASE ASSEMBLY	ICT		67894 AU01624	MTH HRS	19-Jun-2008 1688	O/C	1688		
720006 E2	DIFFUSER CASE ASSEMBLY	ICT		67894 AU01629	MTH HRS	19-Jun-2008 1688	O/C	1688		
720007 E1	1ST LP TURBINE NOZZLE	ICT		60240 AU01611	MTH HRS	19-Jun-2008 1688	O/C	1688		
720007 E2	1ST LP TURBINE NOZZLE	ICT		60240 AU01296	MTH HRS	19-Jun-2008 1688	O/C	1688		
720008 E1	ACCESSORY DRIVE GEARBOX ASSEMBLY	ICT		64591 WL01355	MTH HRS	19-Jun-2008 1688	O/C	1688		
720008 E2	ACCESSORY DRIVE GEARBOX ASSEMBLY	ICT		64591 WL01421	MTH HRS	19-Jun-2008 1688	O/C	1688		
725101 E1	HP COMPRESSOR ROTOR	ICT		61964 HW12850	MTH HRS LDG	19-Jun-2008 1688 1115	6000	921	6194	4974

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
725101 E2	HP COMPRESSOR ROTOR	ICT		61964 HW12817	MTH 19-Jun-2008 HRS 1688 LDG 1133	19-Jun-2008 1688	6000	903	6230	5010
725102 E1	HP TURBINE ROTOR	ICT		64411 RRL0472	MTH 19-Jun-2008 HRS 1688	19-Jun-2008 1688	O/C	1688		
725102 E2	HP TURBINE ROTOR	ICT		64411 RRL0481	MTH 19-Jun-2008 HRS 1688	19-Jun-2008 1688	O/C	1688		
725103 E1	HP TURBINE DISK	ICT		59387 RRL7LD12771	MTH 19-Jun-2008 HRS 1688 LDG 1115	19-Jun-2008 1688	8000	921	8194	6974
725103 E2	HP TURBINE DISK	ICT		59387 RRL7LD12776	MTH 19-Jun-2008 HRS 1688 LDG 1133	19-Jun-2008 1688	8000	903	8230	7010
725501 E1	1ST LP TURBINE DISK	ICT		55531 RRL7S02633	MTH 19-Jun-2008 HRS 1688 LDG 1115	19-Jun-2008 1688	10000	921	10194	8974
725501 E2	1ST LP TURBINE DISK	ICT		55531 RRL7S02624	MTH 19-Jun-2008 HRS 1688 LDG 1133	19-Jun-2008 1688	10000	903	10230	9010
725502 E1	2ND LP TURBINE DISK	ICT		55534 RRL7S02507	MTH 19-Jun-2008 HRS 1688 LDG 1115	19-Jun-2008 1688	10000	921	10194	8974
725502 E2	2ND LP TURBINE DISK	ICT		55534 RRL7S02056	MTH 19-Jun-2008 HRS 1688 LDG 1133	19-Jun-2008 1688	10000	903	10230	9010
733001 LEFT	FUEL FLOW TRANSMITER 9912417-1	*CF		1573-4 1332	MTH 21-Oct-2002	21-Oct-2002	O/C			
733001 RIGHT	FUEL FLOW TRANSMITER 9912417-1	*CF		1573-4 1326	MTH 21-Oct-2002	21-Oct-2002	O/C			
730002 E1	FUEL NOZZLE ASSEMBLY	ICT		50817 BCCIAEC2555	MTH 19-Jun-2008 HRS 1688	19-Jun-2008 1688	O/C	829		
730002 E2	FUEL NOZZLE ASSEMBLY	MCO		50817 BCC1TA02962	MTH 11-Feb-2009 HRS 1827	11-Feb-2009 1827	O/C	0		
730003 E1	SEAL AND FUEL SLINGER	ICT		55608 AU02744	MTH 19-Jun-2008 HRS 1688	19-Jun-2008 1688	O/C	1688		
730003 E2	SEAL AND FUEL SLINGER	ICT		55608 AU02736	MTH 19-Jun-2008 HRS 1688	19-Jun-2008 1688	O/C	1688		
732101 E1	INTEGRATED FUEL CONTROL UNIT	ICT		67985 RF13259591	MTH 19-Jun-2008 HRS 1688	19-Jun-2008 1688	3500	1688	3500	1422.4
732101 E2	INTEGRATED FUEL CONTROL UNIT	ICT		67985 RF13282582	MTH 19-Jun-2008 HRS 1688	19-Jun-2008 1688	3500	1688	3500	1422.4
732301 E1	FUEL FILTER ELECTRICAL INDICATOR	ICT		57847 GE1150	MTH 19-Jun-2008 HRS 1688	19-Jun-2008 1688	O/C	1688		
732301 E2	FUEL FILTER ELECTRICAL INDICATOR	ICT		57847 GE1149	MTH 19-Jun-2008 HRS 1688	19-Jun-2008 1688	O/C	1688		

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
741001 E1 INBOARD	IGNITION EXCITER	ICT		CH92007 CK0200625	MTH HRS	19-Jun-2008 1688	O/C	1688		
741001 E1 OUTBOARD	IGNITION EXCITER	ICT		CH92007 CK0200681	MTH HRS	19-Jun-2008 1688	O/C	1688		
741001 E2 INBOARD	IGNITION EXCITER	ICT		CH92007 CK0200622	MTH HRS	19-Jun-2008 1688	O/C	1688		
741001 E2 OUTBOARD	IGNITION EXCITER	ICT		CH92007 CK0200656	MTH HRS	19-Jun-2008 1688	O/C	1688		
741002 E1	SHORT IGNITER LEAD	*CF		53279 -	MTH HRS	21-Oct-2002 -	O/C			
741002 E2	SHORT IGNITER LEAD			53279 SN-UNKNOWN	MTH HRS	02-Apr-2005 789	O/C	0		
741003 E1	LONG IGNITER LEAD	*CF		53221 -	MTH HRS	21-Oct-2002 -	O/C			
741003 E2	LONG IGNITER LEAD	*CF		53221 SN-UNKNOWN	MTH HRS	21-Oct-2002 -	O/C			
741004 E1 INBOARD	IGNITOR	ICT		CH31956 SN-UNKNOWN	MTH HRS	19-Jun-2008 1688	O/C	352		
741004 E1 OUTBOARD	IGNITOR	ICT		CH31956 SN-UNKNOWN	MTH HRS	19-Jun-2008 1688	O/C	352		
741004 E2 INBOARD	IGNITOR	ICT		CH31956 SN-UNKNOWN	MTH HRS	19-Jun-2008 1688	O/C	352		
741004 E2 OUTBOARD	IGNITOR	ICT		CH31956 SN-UNKNOWN	MTH HRS	19-Jun-2008 1688	O/C	352		
761001	ENGINE SYNC CONTROLLER	*CF		213693 13259134	MTH HRS	21-Oct-2002 -	O/C			
761002	ENGINE SYNC ACTUATOR	*CF		5485-066 13236866	MTH HRS	21-Oct-2002 -	O/C			
772001 LEFT NO. 1	ITT PROBE	ICT		62141 YYF006466	MTH HRS	19-Jun-2008 1688	O/C	1688		
772001 LEFT NO. 2	ITT PROBE	ICT		62141 YYF006467	MTH HRS	19-Jun-2008 1688	O/C	1688		
772001 LEFT NO. 3	ITT PROBE	ICT		62141 YYF006468	MTH HRS	19-Jun-2008 1688	O/C	1688		
772001 LEFT NO. 4	ITT PROBE	ICT		62141 YYF006469	MTH HRS	19-Jun-2008 1688	O/C	1688		
772001 LEFT NO. 5	ITT PROBE	ICT		62141 YYF006470	MTH HRS	19-Jun-2008 1688	O/C	1688		

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
772001 LEFT NO. 6	ITT PROBE	ICT		62141 YYF006471	MTH HRS	19-Jun-2008 1688	O/C	1688		
772002 RIGHT NO. 1 <i>772001 : E2-1</i>	ITT PROBE	ICT		62141 YYF006460	MTH HRS	19-Jun-2008 1688	O/C	1688		
772002 RIGHT NO. 2 <i>772001 : E2-2</i>	ITT PROBE	ICT		62141 YYF006461	MTH HRS	19-Jun-2008 1688	O/C	1688		
772002 RIGHT NO. 3 <i>772001 : E2-3</i>	ITT PROBE	ICT		62141 YYF006462	MTH HRS	19-Jun-2008 1688	O/C	1688		
772002 RIGHT NO. 4 <i>772001 : E2-4</i>	ITT PROBE	ICT		62141 YYF006463	MTH HRS	19-Jun-2008 1688	O/C	1688		
772002 RIGHT NO. 5 <i>772001 : E2-5</i>	ITT PROBE	ICT		62141 YYF006464	MTH HRS	19-Jun-2008 1688	O/C	1688		
772002 RIGHT NO. 6 <i>772001 : E2-6</i>	ITT PROBE	ICT		62141 YYF006465	MTH HRS	19-Jun-2008 1688	O/C	1688		
774001	N1 STANDBY INDICATOR	*CF		10645N01R02 0379A	MTH	21-Oct-2002	O/C			
774002 LEFT AFT <i>774002A : L</i>	CONCENTRATOR UNIT DCU-3010	*CF		822-1278-002 10MOY	MTH	21-Oct-2002	O/C			
774002 LEFT FORWARD	CONCENTRATOR UNIT DCU-3010	*CF		822-1278-002 10JMN	MTH	21-Oct-2002	O/C			
774002 RIGHT AFT <i>774002A : R</i>	CONCENTRATOR UNIT DCU-3010	*CF		822-1278-002 1247H	MTH	21-Oct-2002	O/C			
774002 RIGHT FORWARD	CONCENTRATOR UNIT DCU-3010	*CF		822-1278-002 129H7	MTH	21-Oct-2002	O/C			
774003	N1 COMPUTER	*CF	A	C-13232-1 494	MTH	21-Oct-2002	O/C			
771001 E1	N1 SPEED PICKUP	ICT		50867 YYV1239	MTH HRS	19-Jun-2008 1688	O/C	1688		
771001 E2	N1 SPEED PICKUP	ICT		50867 YYV1196	MTH HRS	19-Jun-2008 1688	O/C	1688		
771002 E1	N2 SPEED PICKUP	ICT		50866 YYV1059	MTH HRS	19-Jun-2008 1688	O/C	1688		
771002 E2	N2 SPEED PICKUP	ICT		50866 YYV1067	MTH HRS	19-Jun-2008 1688	O/C	1688		
783000 LEFT	T/R DEPLOY SWITCH	*CF		602EN602-6 SN-UNKNOWN	MTH	21-Oct-2002	O/C			
783000 RIGHT	T/R DEPLOY SWITCH	*CF		602EN602-6 SN-UNKNOWN	MTH	21-Oct-2002	O/C			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Components

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
783001 LEFT	T/R STOW SWITCH	*CF		602EN602-6 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
783001 RIGHT	T/R STOW SWITCH	*CF		602EN602-6 SN-UNKNOWN		MTH 21-Oct-2002	O/C			
783003 LEFT	ATTENUATOR ACTUATOR	*CF		6317105-13 00534		MTH 21-Oct-2002	O/C			
783003 RIGHT	ATTENUATOR ACTUATOR	MCO		6317105-13 00236		MTH 26-Aug-2003 HRS 321	O/C	0		
793002 LEFT ENGINE	OIL PRESSURE SWITCH 9912178-4	*CF		S1103P89-3 1394		MTH 21-Oct-2002	O/C			
793002 RIGHT ENGINE	OIL PRESSURE SWITCH 9912178-4	*CF		S1103P89-3 1402		MTH 21-Oct-2002	O/C			
793003 LEFT ENGINE	OIL PRESSURE TRANSMITTER	*CF		APTE-304-200G 66881266		MTH 21-Oct-2002	O/C			
793003 RIGHT ENGINE	OIL PRESSURE TRANSMITTER	*CF		APTE-304-200G 668811334		MTH 21-Oct-2002	O/C			
792201 E1	LUBE OIL COOLER	ICT		59857 FC0414		MTH 19-Jun-2008 HRS 1688	O/C	1688		
792201 E2	LUBE OIL COOLER	ICT		59857 FC0420		MTH 19-Jun-2008 HRS 1688	O/C	1688		
792401 E1	LUBE AND SCAVENGE PUMP	ICT		63123 WL01434		MTH 19-Jun-2008 HRS 1688	3500	1688	3500	1422.4
792401 E2	LUBE AND SCAVENGE PUMP	ICT		63123 WL01441		MTH 19-Jun-2008 HRS 1688	3500	1688	3500	1422.4



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
SB 525A-11-02 <i>11SB-02</i>	ENGINE OIL QUANTITY PLACARD REPLACEMENT	MCO		RECOMMENDED	MTH 11-Mar-2004 HRS 484		-			Complete
SB 525A-11-04 <i>11SB-04</i>	GEAR EXTEND SPEED REDUCTION	GNE		MANDATORY	MTH 09-Feb-2007 HRS 1336		A/R			Complete
SB 525A-21-05 <i>21SB-05</i>	TEMPERATURE SENSOR RELOCATION			OPTIONAL	MTH		A/R			
SB 525A-23-03 <i>23SB-03</i>	GARMIN RADIO MODIFICATION	MCO		RECOMMENDED	MTH 26-Aug-2003 HRS 321		-			Complete
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SB 525A-23-04 <i>23SB-04</i>	HONEYWELL KY-196A/KY-196B DUAL VHF COMM SYSTEM UPGRADE	MCO		RECOMMENDED	MTH 26-Aug-2003 HRS 321		-			Complete
SB 525A-23-05 <i>23SB-05</i>	GARMIN RADIO REPLACEMENT			OPTIONAL	MTH 07-Apr-2006 HRS 1173		-			N/A
NOT APPLICABLE										
SB 525A-23-07 <i>23SB-07</i>	GARMIN GTX330/330D TRANSPONDER SOFTWARE VERSION 3.03 UPGRADE			MANDATORY	MTH 02-Apr-2005 HRS 789		-			N/A
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SL 525A-23-01 R1 <i>23SL-01 : 525A1</i>	TRANSMITTAL OF GARMIN SERVICE BULLETIN 0218, NEW SOFTWARE VERSION 3.00 (MAIN) FOR 400/500 SERIES UNITS AND 3.00(GPS) FOR 400/500 SERIES UNITS			OPTIONAL	MTH 07-Apr-2006 HRS 1173		-			N/A
NOT APPLICABLE										
SB 525A-24-03 <i>24SB-03</i>	AVIONICS EMERGENCY BUS RELAY IMPROVEMENT			DISCRETIONARY	MTH		A/R			
SL 525A-24-02 <i>24SL-02</i>	WIRE BUNDLE INSPECTION			RECOMMENDED	MTH HRS		300		2139	61.4
SB 525A-25-03 <i>25SB-03</i>	EMERGENCY LOCATOR TRANSMITTER (ELT) WIRING MODIFICATION			OPTIONAL	MTH		-			
SB 525A-25-04 <i>25SB-04</i>	THREE FREQUENCY ELT WITH NAV INTERFACE INSTALLATION			OPTIONAL	MTH		-			
SB 525A-25-05 R1 <i>25SB-05 : 525A1</i>	GLARESHIELD LEATHER STRIP INSTALLATION			OPTIONAL	MTH		-			
SB 525A-25-05 <i>25SB-05</i>	GLARESHIELD LEATHER STRIP INSTALLATION	MCO		OPTIONAL	MTH 06-Aug-2004 HRS 630		-			Complete
SB 525A-25-06 <i>25SB-06</i>	AFT CABIN INSULATION MOD			OPTIONAL	MTH		-			
SB 525A-25-07 <i>25SB-07</i>	AIRCELL ANTENA INSTALLATION IMPROVEMENT			OPTIONAL	MTH		-			
SB 525A-25-08 <i>25SB-08</i>	PASSENGER SEAT GEAR AND BACKREST LATCH PIN REPLACEMENT			OPTIONAL	MTH		-			
SL 525A-25-01 <i>25SL-01</i>	TRANSMITTAL OF PACIFIC SCIENTIFIC AEROSPACE SERVICE BULLETIN SB 25-111432, INFORMATION REGARDING THE POTENTIAL FAILURE OF THE GUARDED ROTARY BUCKLE PLASTIC HANDLE	ICT		MANDATORY	MTH 19-Jun-2008 HRS 1688		A/R			Complete
SL 525A-25-02 <i>25SL-02</i>	INSPECTION OF THE BACKREST LATCH PLATES	KPW A		MANDATORY	MTH 12-Feb-2010 HRS 2052 LDG 1206		A/R			Complete
SB 525A-26-02 <i>26SB-02</i>	FIRE BOTTLE IDENTIFICATION SLEEVE INSTALLATION	SWF		MANDATORY	MTH 21-Jun-2005 HRS 837		-			Complete
SB 525A-27-03 R1 <i>27SB-03 : 525A1</i>	FLAP OVERRIDE SWITCH INSTALLATION	MCO		RECOMMENDED	MTH 26-Aug-2003 HRS 321		-			Complete
SB 525A-27-04 <i>27SB-04</i>	AILERON CABLE AND FAIRLEAD TUBE REPLACEMENT			RECOMMENDED	HRS		300		2191	113.4
SB 525A-27-07 <i>27SB-07</i>	ELEVATOR TRIM POINTER IMPROVEMENT			OPTIONAL	MTH		-			

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
SB 525A-27-08 <i>27SB-08</i>	RUDDER BIAS SIMPLIFICATION			OPTIONAL		MTH	A/R			
SB 525A-27-09 <i>27SB-09</i>	ELEVATOR TRIM POINTER ASSEMBLY IMPROVEMENT			OPTIONAL		MTH	A/R			
SB 525A-27-10 <i>27SB-10</i>	INSPECTION OF TAILCONE WIRE BUNDLE	APA		RECOMMENDED		MTH HRS 1498	17-Oct-2007	A/R		Complete
SL 525A-27-03 <i>27SL-03</i>	RUDDER BIAS PNEUMATIC LINE CLAMP INSPECTION	MCO		RECOMMENDED		MTH HRS 630	06-Aug-2004	-		Complete
SL 525A-27-05 <i>27SL-05</i>	FLAP PUSHROD SAFETY WIRE INSPECTION	ICT		RECOMMENDED		MTH HRS 1688	19-Jun-2008	A/R		Complete
SB 525A-28-02 <i>28SB-02</i>	FUEL BOOST PUMP ANNUNCIATION IMPROVEMENT	MCO		DISCRETIONARY		MTH HRS 630	06-Aug-2004	-		Complete
SB 525A-28-03 <i>28SB-03</i>	WING FUEL BOOST PUMP WIRE ROUTING IMPROVEMENT	MCO		MANDATORY		MTH HRS 539	03-May-2004	-		Complete
SB 525A-28-04 <i>28SB-04</i>	FIREWALL SHUTOFF VALVE REPLACEMENT AND FIREWALL SHUTOFF VALVE BRACKET MODIFICATION			OPTIONAL		MTH		A/R		
SL 525A-28-02 <i>28SL-02</i>	FUEL LINE CLEARANCE IMPROVEMENT	APA		MANDATORY		MTH HRS 1938	09-Jul-2009	A/R		Complete
SB 525A-29-04 R2 <i>29SB-04 : 525R2</i>	HYDRAULIC RELIEF VALVE INLET NUT INSPECTION/REPLACEMENT			CANCELLED		MTH HRS		36 1200		
SERVICE BULLETIN CANCELLED.										
SB 525A-32-07 <i>32SB-07</i>	BEARING REPLACEMENT			MANDATORY		MTH HRS 920	05-Oct-2005	-		Complete
SB 525A-32-10 <i>32SB-10</i>	MAIN LANDING GEAR ACTUATOR EXTEND HOSE IMPROVEMENT	APA		RECOMMENDED		MTH HRS 1538	08-Nov-2007	A/R		Complete
SB 525A-32-11 <i>32SB-11</i>	BRAKE HYDRAULIC AND PNEUMATIC TUBE IMPROVEMENT	ICT		MANDATORY		MTH HRS 1373	26-May-2007	A/R		Complete
SB 525A-32-12 <i>32SB-12</i>	IMPROVEMENT TO THE PUSHROD ASSEMBLY ON THE MAIN LANDING GEAR DOOR	APA		MANDATORY		MTH HRS 1538	08-Nov-2007	A/R		Complete
ASL 525A-32-11 R1 <i>32SLA11 : 525A1</i>	MAIN LANDING GEAR DOOR PUSHROD INSPECTION	GNE		MANDATORY		MTH HRS 1336	09-Feb-2007	A/R		Complete
SL 525A-32-03 <i>32SL-03</i>	HYDRAULIC TUBE INSPECTION	ICT		RECOMMENDED		MTH HRS 15	21-Oct-2002	-		Complete
SL 525A-32-07 <i>32SL-07</i>	BRAKE SUPPLY LINE FILTER INSPECTION	GNE		RECOMMENDED		MTH HRS 1336	09-Feb-2007	A/R		Complete
SL 525A-32-08 R1 <i>32SL-08 : 525A1</i>	NOSE LANDING GEAR ICE PROTECTION BOOT INSTALLATION			OPTIONAL		MTH		-		
SL 525A-32-12 <i>32SL-12</i>	TRANSMITTAL OF GOODRICH SERVICE LETTER 2056	APA		RECOMMENDED		MTH HRS 1782	12-Dec-2008	A/R		Complete
SL 525A-32-13 R1 <i>32SL-13 : 525A1</i>	MAIN LANDING GEAR DOOR PUSHROD SAFETY WIRE INSPECTION	APA		RECOMMENDED		MTH HRS 2051	06-Jan-2010	A/R		Complete
SL 525A-32-14 R1 <i>32SL-14 : 525A1</i>	AUXILIARY BRAKE TUBE INSPECTION			RECOMMENDED		MTH HRS		300		
SERVICE BULLETIN ON HOLD.										
SL 525A-32-17 <i>32SL-17</i>	EMERGENCY GEAR RELEASE INSPECTION			MANDATORY		MTH HRS		24 400	01-Dec-2011 2409.77	New Req
SB 525A-33-02 <i>33SB-02</i>	WING TIP ANTICOLLISION LIGHT MOD	MCO		RECOMMENDED		MTH HRS 630	06-Aug-2004	-		Complete
SB 525A-33-03 <i>33SB-03</i>	CHART LIGHT MODIFICATION			OPTIONAL		MTH		-		
SB 525A-34-01 R1 <i>34SB-01 : 525A1</i>	RVSM OPERATION MOD	*CF		OPTIONAL		MTH		-		

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
SB 525A-34-09 <i>34SB-09</i>	ATTITUDE INDICATOR AND HORIZONTAL SITUATION INDICATOR MODIFICATION	MCO		RECOMMENDED	MTH HRS	06-Aug-2004 630	-			Complete
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
SB 525A-34-11 <i>34SB-11</i>	RADIO ALTIMETER CONVERTER UPGRADE	MCO		DISCRETIONARY	MTH HRS	06-Aug-2004 630	-			Complete
SB 525A-34-14 <i>34SB-14</i>	GARMIN GNS-530A RADIOS/FMS & GTX-330D TRANSPONDER INSTALLATION			OPTIONAL	MTH HRS	07-Apr-2006 1173	-			N/A
NOT APPLICABLE										
SB 525A-34-15 <i>34SB-15</i>	MST-67A DIVERSITY TRANSPONDER INSTALLATION			OPTIONAL	MTH		-			
SB 525A-34-16 <i>34SB-16</i>	GARMIN GTX-330D TRANSPONDER INSTALLATION UPGRADE			OPTIONAL	MTH		A/R			
SB 525A-34-17 R2 <i>34SB-17 : 525R2</i>	GTX-330D TRANSP SFTGRD TO 4.01			OPTIONAL	MTH		A/R			
SB 525A-34-18 <i>34SB-18</i>	UNIVERSAL UNS-1K SOFTWARE UPGRADE TO 604.7			OPTIONAL	MTH		A/R			
SB 525A-34-19 R1 <i>34SB-19 : 525A1</i>	TERRAIN AWARENESS WARNING SYSTEM (TAWS) UPGRADE TO SOFTWARE LEVEL 1.13			OPTIONAL	MTH		A/R			
SB 525A-34-20 R2 <i>34SB-20 : 525A2</i>	FILE SERVER INSTALLATION AND MULTIFUNCTION DISPLAY (MFD) UPDATE FOR CHARTS AND XM SATELLITE WEATHER			OPTIONAL	MTH		A/R			
SB 525A-38-01 <i>38SB-01</i>	PILOT'S RELIEF TUBE IMPROVEMENT			OPTIONAL	MTH		-			
SB 525A-52-03 R1 <i>52SB-03 : 525R1</i>	CABIN ENTRY DOOR HANDLE POSITION SWITCH INSTALLATION			OPTIONAL	MTH		A/R			
ASL 525A-52-01 <i>52SLA01</i>	EMERGENCY DOOR INSPECTION	APA		MANDATORY	MTH HRS	20-Dec-2007 1590	A/R			Complete
SB 525A-53-01 <i>53SB-01</i>	DISABLE THE COCKPIT MOUNTED RELIEF TUBE(S)			SUPERSEDED	MTH HRS	12-Sep-2007 1485	A/R			Complete
ASL 525A-53-04 <i>53SLA04</i>	RELIEF TUBE CORROSION	GNE		MANDATORY	MTH HRS	09-Feb-2007 1336	A/R			Complete
ASL 525A-53-05 R5 <i>53SLA05 : 525A5</i>	RELIEF TUBE CORROSION INSPECTION	ICT		SUPERSEDED	MTH HRS	19-Jun-2008 1688	A/R			Complete
ASL 525A-53-05 <i>53SLA05</i>	RELIEF TUBE CORROSION INSPECTION			MANDATORY	MTH HRS	12-Sep-2007 1485	A/R			N/A
NOT APPLICABLE BY COMPONENT SERIAL NUMBER.										
SL 525A-53-09 <i>53SL-09</i>	INTERCOSTAL DRAINAGE PATH INSPECTION			RECOMMENDED	HRS		300		2337	259.4
SB 525A-54-01 LEFT <i>54SB-01 : L</i>	FIREWALL BOX REPAIR	ICT			MTH HRS	19-Jun-2008 1688	-			Complete
SB 525A-54-01 RIGHT <i>54SB-01 : R</i>	FIREWALL BOX REPAIR	ICT			MTH HRS	19-Jun-2008 1688	-			Complete
SB 525A-57-01 <i>57SB-01</i>	CENTER WING NOISE REDUCTION IMPROVEMENT			DISCRETIONARY	MTH		-			
SL 525A-57-01 <i>57SL-01</i>	ACCESS DOOR DRAINAGE IMPROVEMENT			RECOMMENDED	MTH HRS	08-Apr-2006 1173	-			Complete
SB 525A-71-02 R1 <i>71SB-02 : 525A1</i>	UPPER ENGINE COWL SUPPORT MODIFICATION			OPTIONAL	MTH		-			
SB 525A-78-01 <i>78SB-01</i>	ENGINE EXHAUST NOZZLE DEFLECTOR TAB INSTALLATION	CCS		DISCRETIONARY	MTH HRS	04-Jul-2003 254	-			Complete
SB 525A-78-02 R1	THRUST ATTENUATOR PADDLE IMPROVEMENT			MANDATORY	MTH HRS		12 300		05-Feb-2011 2309.95	New Req
SB 525A-78-02 <i>78SB-02</i>	THRUST ATTENUATOR PADDLE IMPROVEMENT	ICT		MANDATORY	MTH HRS	19-Dec-2009 2044	A/R			Complete

*NOTE: Item Codes in italics show pre-migration CESCOM item codes and position (provided for cross-reference). Remains calculated from Print Date for calendar items. The estimated cost and man hours listed on the CESCOM reports are generic and are for information only.



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Service Bulletins

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
ASL 525A-78-01 R1 <i>78SLA01 : 525R1</i>	THRUST ATTENUATOR PADDLE INSPECTION ICT			MANDATORY		MTH 19-Dec-2009 HRS 2044		A/R		Complete
SB 525A-79-02 <i>79SB-02</i>	ENGINE GEARBOX BREATHER LINE INSTALLATION DISCRETIONARY					MTH	-			



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Airworthiness Directives

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
AD 1998-25-02 34AD-02 : 525	BFGOODRICH SKYWATCH SKY497	ICT			MTH HRS	21-Oct-2002 15	A/R			Complete
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
AD 1999-08-21 35AD-01 : 525	PURITAN-BENNETT AERO SYSTEMS CO.	ICT			MTH HRS	21-Oct-2002 15	A/R			Complete
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
AD 2001-23-17 34AD-03	GARMIN GNS 430	ICT			MTH HRS	21-Oct-2002 15	A/R			Complete
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
AD 2002-20-09 31AD-01	COLLINS AFD-3010 AFD UNITS	ICT			MTH HRS	21-Oct-2002 15	A/R			Complete
AD 2003-13-08 34AD-01	TAWS 8000 TERRAIN AWARENESS	MCO			MTH HRS	26-Aug-2003 321	A/R			Complete
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
AD 2004-08-15 34AD-02	TAWS 8000 TERRAIN AWARENESS	MCO			MTH HRS	06-Aug-2004 630	A/R			Complete
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
AD 23-15	EASA AD2005-0021				MTH HRS	05-Oct-2005 920	-			N/A
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
AD 2003-26-14 26AD-01	REMOVE FROM SERVICE FIRE EXTINGUISHERS THAT HAVE INCOMPLETE CRIMPING OF SIPHON TUBE	ICT			MTH HRS	26-May-2007 1373	A/R			N/A
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
AD 2005-17-11 26AD-02	PREVENT INCORRECT INSTALLATION OF WIRES TO THE ENGINE FIRE EXTINGUISHER BOTTLES			MANDATORY	MTH HRS	05-Oct-2005 920	-			Complete
PREVIOUSLY COMPLIED WITH.										
AD 2005-01-19 34AD-08	TO PREVENT INTERROGATING A/C FROM POSSIBLY RECEIVING INACCURATE REPLIES FROM A/C EQUIPPED WITH GARMIN GTX33/33D/330/330D MODE S TRANSPONDERS			MANDATORY	MTH HRS	08-Jun-2007 1375	A/R			N/A
NOT APPLICABLE-EQUIPMENT NOT INSTALLED										
AD 1974-08-09 R2	WASTE RECEPTACLE INSPECTION	KPW A		MANDATORY	MTH HRS LDG	12-Feb-2010 2052 1206	1000		3052	Complete Recurring Complete
AD 2008-03-10 53AD-01	INSPECT THE LOWER WING SKIN STRUCTURE, FORWARD WING SPAR, LOWER FUSELAGE SKIN, FAIRINGS, AND THE EXTERNAL FAIRING FRAMES FOR CORROSION; REPAIR ANY DAMAGE FOUND; APPLY A CORROSION INHIBITIVE SEALANT TO THE FUSELAGE FAIRINGS BEFORE REINSTALLING; AND DISABLE THE COCKPIT MOUNTED PILOT RELIEF TUBE	ICT		AIRWORTHINESS	MTH HRS	19-Jun-2008 1688	A/R			Complete
AD 2009-24-13 78AD-01	DETECT AND CORRECT LOOSE AND DAMAGED FASTENERS AND CRACKS IN THE THRUST ATTENUATOR PADDLES	ICT		MANDATORY	MTH HRS	19-Dec-2009 2044	A/R			Complete



CESCOM 10 - Aircraft Status Report

Owner: **AERO JAN**
 Aircraft Model: **525A - CJ2**
 Aircraft Serial: **525A-0114** Unit: **0114** Reg No: **N726RP**
 Airworthiness: **21-Oct-2002**
 Print Date: **22-Mar-2010 4:19PM**

Tracking Rate	Hours	Events/ Landing	Last Actual Date	Average Daily Utilization
AIRCRAFT	2077.6	1220	22-Mar-2010	.82
ENG 1	2077.6	1123	22-Mar-2010	.82
ENG 2	2077.6	1105	22-Mar-2010	.82
AIR COND	845.7		22-Mar-2010	1.22

Factory Installed

Item Code Position	Description Drawing # / Task #	City	Mod Lvl	Part Number Part Serial No	Est Cost Est Hours	C/W Time 1 C/W Time 2	TBO 1 TBO 2	TSO 1 TSO 2	Due 1 Due 2	Remains Remains
23FO631W <i>23FO631 : W</i>	HF COMM-KHF950 FACTORY OPTION	*CF		631W FO		MTH 21-Oct-2002	-			
23FO634K <i>23FO634 : K</i>	RECORDER-COCKPIT VOICE LORAL/FAIRCHILD A200S FACTORY OPTION	*CF		634K FO		MTH 21-Oct-2002	-			
23FO674B <i>23FO674 : B</i>	SPEAKER-COCKPIT MUTE FACTORY OPTION	*CF		674B FO		MTH 21-Oct-2002	-			
24FO186E <i>24FO186 : E</i>	BATTERY-LEAD ACID CONCORDE (EXCHANGE) FACTORY OPTION	*CF		186E FO		MTH 21-Oct-2002	-			
25FO50G <i>25FO50 : G</i>	LIGHTING-INDIRECT FACTORY OPTION	*CF		50G FO		MTH 21-Oct-2002	-			
25FO720B	VINYL COVERED OVERHEAD FACTORY OPTION	*CF		720B FO		MTH 21-Oct-2002	-			
25FO728B	CHANPAGNE COLORED CKP & CBN DO OR TRIMS FACTORY OPTION	*CF		728B FO		MTH 21-Oct-2002	-			
28FO-36	FUEL CAPS-LOCKING FACTORY OPTION	*CF		36 FO		MTH 21-Oct-2002	-			
33FO056B <i>33FO056 : B</i>	LIGHTS-PULSE FACTORY OPTION	*CF		56B FO		MTH 21-Oct-2002	-			
34FO607F <i>34FO607 : F</i>	THIRD DISPLAY-COLLINS (EXCHNG) FACTORY OPTION	*CF		607F FO		MTH 21-Oct-2002	-			
34FO801	KIT FOR BF GOODRICH, WX-1000E EFIS STORMSCOPE FACTORY OPTION	*CF		801 FO		MTH 21-Oct-2002	-			
35FO066F <i>35FO066 : F</i>	OXYGEN-50CU FT BOTTLE FACTORY OPTION	*CF		66F FO		MTH 21-Oct-2002	-			
77FO680	N1 COMPUTER-SAFE FLIGHT FACTORY OPTION	*CF		680 FO		MTH 21-Oct-2002	-			